





report date: 2024-03-29

#### General information

Make	JAGUAR
Model	X-TYPE SPORT
Colour	Blue
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	152 BHP
Max. torque	360 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg



CarCheck.co.uk page 1/14



report date: 2024-03-29

# Internet history

#### Entry 1

Date 2021-10-02

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

#### **MOT** history

**MOT #22** 2023-12-21 13:33

**MOT test number** 676448982576

**Result** ✓ Passed

Next expiry date 2024-12-20

Advice Front Oil leak, but not excessive engine oil leak not excessive. (8.4.1 (a) (i))

**Advice** Front windscreen light scratching.

**Advice** Nearside Integral body structure is corroded but structural rigidity is not significantly reduced outer sill corroded. (6.1.1 (c) (i))

Advice Front Steering system slightly rough (2.1.1 (a))

**MOT #21** 2022-12-14 16:39

MOT test number 291308688656

Result 

Passed

**Advice** Corrosion to vehicle underbody

**Advice** Underseal to sills

MOT #20 2022-10-28 12:24

**MOT test number** 857717411304

**Result** X Failed

**Advice** Underseal to sills

MAJOR Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

**MAJOR** Offside Front Inner Seat belt anchorage prescribed area strength or continuity significantly

reduced sill (fibre glassed) (7.1.1 (a) (i))

CarCheck.co.uk page 3/14



report date: 2024-03-29

**MOT #19** 2022-09-23 13:42

**MOT test number** 534485045828

Result X Failed

MAJOR Offside Front Upper Coil spring fractured or broken (5.3.1 (b) (i))

MAJOR Nearside Rear Brake pipe excessively corroded to flexi (1.1.11 (c))

MAJOR Offside Rear Lower Suspension arm corroded and seriously weakened wish bone (5.3.3 (b) (i))

**MAJOR** Offside Front Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength sill (5.3.6 (a) (i))

**MAJOR** Offside Rear Brake pipe excessively corroded to flexi (1.1.11 (c))

MOT #18 2021-10-07 08:04

**MOT test number** 965678233777

**MOT #17** 2021-10-05 15:19

MOT test number 367088632982

Result × Failed

**MAJOR** Offside Rear Fluid leak harmful to the environment or a risk to other road users fuel leak (8.4.1 (a) (i))

**MAJOR** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))

**MAJOR** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength inner sill (5.3.6 (a) (i))

**MOT #16** 2020-08-07 14:17

**MOT test number** 278193004244

**Result** ✓ Passed

CarCheck.co.uk page 4/14



report date: 2024-03-29

**MOT #15** 2020-08-07 10:41

**MOT test number** 978901783682

Result X Failed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Offside Rear Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #14** 2019-08-10 08:46

MOT test number 134775295160

Result 

Passed

Advice Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement mounts (5.3.4 (a) (i))

MOT #13 2019-08-10 08:46

MOT test number 287915902393

**Result** X Failed

**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

Advice Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement mounts (5.3.4

(a) (i))

**MOT #12** 2018-08-07 10:15

MOT test number 402255636885

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #11

MOT test number

663627150871

Result

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #10

MOT test number

202348860856

Result

Fail Offside Rear Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Offside Rear Brake pipe slightly corroded (3.6.B.2c)

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

MOT #9

MOT test number

475927000923

Result

Advice Offside rear tyre is wearing low on tread on inside edge

**MOT #8** 2015-07-27 16:26 **MOT** test number 750957885383 Result ✓ Passed MOT #7 2014-07-30 15:08 **MOT test number** 376421814491 ✓ Passed Result **MOT** #6 2013-07-30 15:06 **MOT test number** 565871913212 Result ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #4** 2012-05-09 16:06 **MOT** test number 768240832105 Result × Failed Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b) Advice Rear Brake pad(s) wearing thin (3.5.1g) Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Pass with rectification Nearside Headlamp aim too low (1.8) Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b) Advice Front Brake pad(s) wearing thin (3.5.1g) **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Pass with rectification Offside Headlamp aim too low (1.8)

MOT #3

MOT test number

897033041144

Result

Notice Nail in nearside rear tyre

CarCheck.co.uk page 7/14



report date: 2024-03-29

MOT #2 2010-04-26 16:07

**MOT test number** 360576110108

**Result** ✓ Passed

**MOT #1** 2009-04-27 14:35

MOT test number 283967619414

CarCheck.co.uk page 8/14



report date: 2024-03-29

#### Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

<b>IWO</b>		la i a t	
U JAAV I	101	misi	$\mathbf{O} \mathbf{I} \mathbf{V}$

For how long did the current and previous owner(s) have this JAGUAR? How many owner	
have? Check it in the premium report and see all owner registrations. Download the full it	report <u>here</u> .
nessess.	
***************************************	
***************************************	
HEREERS	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

#### Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-04-28
Last registration	2023-12-21
Complete history	See info



Registration #1	2006-04-28	13 mi
Registration #2	2009-04-27	24.698 mi
Registration #3	2010-04-26	35.076 mi
Registration #4	2011-05-23	49.183 mi
Registration #5	2012-05-09	62.448 mi
Registration #6	2012-05-14	62.614 mi
Registration #7	2013-07-30	67.561 mi
Registration #8	2014-07-30	71.305 mi
Registration #9	2015-07-27	75.685 mi
Registration #10	2016-08-03	79.244 mi
Registration #11	2017-08-09	82.861 mi
Registration #12	2017-08-10	82.865 mi
Registration #13		11.777 esi
Registration #14		11.777 es
Registration #15		11.777 esi
Registration #16		11.777 es
Registration #17		11.777 esi
Registration #18		11.777 es
Registration #19		11.777 esi
Registration #20		0.77 44
Registration #21		11.777 es
Registration #22		11.771 44
Registration #23		11.777 es
Registration #24		77.777 au

More info >



MA06KWV report date: 2024-03-29

Safety ratings

NCAP rating	***
-------------	-----

**Video** <u>see crash video</u>



# Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2035 kg

# Additional information

Fuel tank capacity	61
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	060203201501BG

CarCheck.co.uk page 14/14