



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	TRAFIC LL29 DCI 115 PV LWB LC
Colour	White
Year of manufacture	2014
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.996 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	37.7 mpg
CO2 emission	198 g/km
CO2 label	J






Internet history

Entry 2


Date	2021-10-29
Pictures	16
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-10-14
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-16
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	5
Total items failed	2

MOT #8	2023-08-15 11:20
MOT test number	198486849166
Result	✓ Passed
Next expiry date	2024-08-16
Advice	Nearside Front Outer Track rod end ball joint has slight play Slight play in track rod end at time of test,owner advised (2.1.3 (b) (i))
Advice	Nearside Front Outer Tyre slightly damaged/cracking or perishing Outer wall has slight kerb damage (5.2.3 (d) (ii))

MOT #7	2022-08-17 13:13
MOT test number	429912637074
Result	✓ Passed

MOT #6	2021-08-17 11:33
MOT test number	920689535926
Result	✓ Passed

MOT #5	2021-08-17 11:33
MOT test number	346944126182
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Pass with rectification	Nearside Rear Stop lamp(s) light intensity significantly reduced (4.3.3 (a) (ii))



MOT #4	2020-08-29 08:27
---------------	------------------

MOT test number	300493642957
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2019-09-12 11:47
---------------	------------------

MOT test number	148260022797
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Front Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))
---------------	--

Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	---

Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
---------------	--

MOT #2	2018-09-20 08:01
---------------	------------------

MOT test number	175670689212
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2017-09-14 14:29
---------------	------------------

MOT test number	910856054239
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
16 August 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	16 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	HY64XYO
Plate since	2019-09-28
Current registration	HY64XYO
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-09-29
Last registration	2023-08-15
Complete history	See info



Registration #1	2014-09-29	25 mi
Registration #2	2017-09-14	37.264 mi
Registration #3	2018-09-20	48.895 mi
Registration #4	2019-09-12	60.894 mi
Registration #5	2020-08-29	75.291 mi
Registration #6	2021-08-17	77.992 mi
Registration #7	2022-08-29	78.277 mi
Registration #8	2023-08-15	78.277 mi
Registration #9	2023-08-15	78.277 mi
Registration #10	2023-08-15	78.277 mi
Registration #11	2023-08-15	78.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	58%
Children	79%
Pedestrian	28%
Safety systems	14%
Overall rating	51%
Video	see crash video



Dimensions & weight

Width	1904 mm
Height	1962 mm
Length	5182 mm
Max. allowed weight	3030 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	C164212