



report date: 2024-03-28

General information

Make	LAND ROVER
Model	DEFENDER TD XS STATION WAGON
Colour	Black
Year of manufacture	2012
Top speed	82 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	121 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	29.7 mpg
Consumption combined	25.4 mpg



LABEL UNKNOWN



Internet history

Entry 4

Date 2023-12-30

Pictures 12

Listing price [View report](#)



source: cargurus.co.uk

Entry 3

Date 2023-09-26

Pictures 24

Listing price [View report](#)




source: cargurus.co.uk

Entry 2

Date 2022-12-02

Pictures 5

Listing price [View report](#)



source: cargurus.co.uk

Entry 1

Date 2021-10-05
CarCheck.co.uk

Pictures

26

Listing price

[View report](#)



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-24
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	10
Total items failed	8

MOT #13	2023-09-25 14:58
MOT test number	747537094567
Result	✓ Passed
Next expiry date	2024-09-24

MOT #12	2022-10-26 13:28
MOT test number	214755197717
Result	✓ Passed

MOT #11	2021-10-02 11:35
MOT test number	971970871603
Result	✓ Passed

MOT #10	2020-10-01 14:01
MOT test number	739995418021
Result	✓ Passed

MOT #9	2020-01-15 13:16
MOT test number	556330696128
Result	✓ Passed

Advice Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

Advice Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**MOT #8** 2018-10-25 10:28**MOT test number** 951358024133**Result** ✓ Passed

- Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush lower (5.3.2 (c))
- Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #7 2018-10-25 09:11**MOT test number** 983363894511**Result** ✗ Failed

- Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))
- Advice** Nearside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Rear Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush lower (5.3.2 (c))

MOT #6 2017-09-08 06:57**MOT test number** 991532100121**Result** ✓ Passed

**MOT #5** 2017-09-07 13:10**MOT test number** 732419877493**Result** ✗ Failed

- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Headlamp aim too high (1.8)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Headlamp aim too high (1.8)

MOT #4 2016-09-27 14:51**MOT test number** 220328920972**Result** ✓ Passed**MOT #3** 2016-01-25 11:57**MOT test number** 784234831703**Result** ✓ Passed**MOT #2** 2014-12-23 12:11**MOT test number** 908967154393**Result** ✓ Passed**MOT #1** 2014-12-23 12:11**MOT test number** 196157554388**Result** ✗ Failed

- Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)
- Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
24 September 2024

Tax status		Valid until 1 October
Days left		156
MOT expiry date		24 September 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	RJ61VBC
Plate since	2024-03-28
Current registration	RJ61VBC
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-01-14
Last registration	2023-09-25
Complete history	See info



Registration #1	2012-01-14	28 mi
Registration #2	2014-12-23	36.634 mi
Registration #3	2016-01-25	43.385 mi
Registration #4	2016-09-27	46.322 mi
Registration #5	2017-09-07	50.236 mi
Registration #6	2017-09-08	50.236 mi
Registration #7	2018-10-25	53.653 mi
Registration #8	2018-10-25	53.653 mi
Registration #9	2020-01-15	57.345 mi
Registration #10	2020-01-15	57.345 mi
Registration #11	2020-01-15	57.345 mi
Registration #12	2020-01-15	57.345 mi
Registration #13	2020-01-15	57.345 mi
Registration #14	2020-01-15	57.345 mi
Registration #15	2020-01-15	57.345 mi
Registration #16	2020-01-15	57.345 mi
Registration #17	2020-01-15	57.345 mi

More info >



Dimensions & weight

Width	1790 mm
Height	2181 mm
Length	4625 mm
Wheel base	2794 mm
Kerb weight	2111 kg
Max. allowed weight	3050 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	7
Number of axles	2
Engine number	110907005303244DT