





report date: 2024-03-29

General information

Make	VOLKSWAGEN	
Model	TRANSPORTER T28 TDI P/V HIGHLINE BMT	
Colour	Blue	
Year of manufacture	2017	
Top speed	98 mph	
0 - 100 km/h	11.5 seconds	
0 - 60 mph	15.3 seconds	
Gearbox	5 speed Manual	

Engine & fuel consumption

Power	110 kW / 150 HP / 101 BHP
Max. torque	340 Nm at 1.500 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.9 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/11



DA17AYN

report date: 2024-03-29


Internet history

Entry 2

Date 2022-01-15

Pictures 61

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-11-06

Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

DANGEROUS

worn (5.3.4 (a) (i))

Advice

MOT expiry date	2024-11-06
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	10
Total items failed	0

MOT #6	2023-10-18 13:52
MOT test number	734246266417
Result	✓ Passed
Next expiry date	2024-11-06
Advice Offside Front Suspension arm pin or bush worn but not resulting in exworn (5.3.4 (a) (i))	cessive movement rear bush
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush worn (5.3.4 (a) (i))	
Advice Nearside Front Coil spring corroded and offside front (5.3.1 (b) (i))	
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #5	2023-10-18 09:37
MOT test number	511567461055
Result	× Failed
Advice Nearside Front Suspension arm pin or bush worn but no bush worn (5.3.4 (a) (i))	ot resulting in excessive movement rear
Advice Nearside Front Coil spring corroded and offside front (5	5.3.1 (b) (i))
Advice Offside Rear Child Seat fitted not allowing full inspection	on of adult belt

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush

Nearside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



MOT test number

DA17AYN report date: 2024-03-29

439362324879

MOT #4 2022-11-07 16:29

Result ✓ Passed

MOT #3 2022-06-30 10:13

985764238927 **MOT** test number

Result ✓ Passed

MOT #2 2021-02-18 16:16

599892412935 **MOT test number**

Result ✓ Passed

MOT #1 2020-05-23 11:18

588428436161 **MOT test number**

Result ✓ Passed

Advice

COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	6 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 5/11



DA17AYN


report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra VOLKSWAGEN salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

Farehard language dial the account and arraying account of the VOLKOWA CENS Have a	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	AIR SIE
Plate since	
Current registration	OK SIL
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-05-31
Last registration	2023-10-18
Complete history	See info



Registration #1	2017-05-31	20 mi
Registration #2	2021-02-18	51.399 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5		D.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1990 mm
Length	4892 mm
Wheel base	3000 mm
Kerb weight	1942 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
CarChack calle	nago 11/11

CarCheck.co.uk page 11/11

Number of seats	3
Number of axles	2
Engine number	CXGB047001