



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT TDI SPORT
Colour	Silver
Year of manufacture	2007
Top speed	128 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg
CO2 emission	172 g/km
CO2 label	H





MOT history

MOT expiry date	2024-07-31
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	22
Total items failed	15

MOT #13	2023-08-01 09:04
MOT test number	945260934206
Result	✓ Passed
Next expiry date	2024-07-31
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #12	2023-07-31 13:33
MOT test number	734061325845
Result	✗ Failed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Fail	Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
Fail	Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Offside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
Fail	Nearside Rear Seat belt not functioning as intended (7.1.2 (c))
Fail	Nearside Rear Service brake excessively binding (1.2.1 (f))
Fail	Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
Fail	Offside Rear Tyre has ply or cords exposed 235/45x17 (5.2.3 (d) (ii))

**MOT #11** 2022-02-03 11:25**MOT test number** 173784298221**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2021-02-02 12:40**MOT test number** 846421520305**Result** ✓ Passed**Advice** Rear both rear tyres miss shaped and feathered**MOT #9** 2020-01-10 14:19**MOT test number** 119630893220**Result** ✓ Passed**MOT #8** 2015-12-03 11:02**MOT test number** 565925373700**Result** ✓ Passed**MOT #7** 2014-10-20 11:49**MOT test number** 549033094203**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #6	2014-10-17 14:14
MOT test number	988330294262
Result	✗ Failed
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
Notice	Offside and nearside rear tyres have worn completly bald on the inner edges
Advice	Offside Rear Shock absorber has a light misting of oil (2.7.3)
Fail	Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
Notice	Engine covers fitted obscuring some components in the engine bay
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Headlamp aim too low and too far to the left. (1.8)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components

MOT #5	2013-10-11 11:16
MOT test number	859534883276
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4	2012-10-15 11:41
MOT test number	878389482265
Result	✓ Passed



MOT #3 2011-10-01 10:16

MOT test number 909354471235

Result ✓ Passed

MOT #2 2011-10-01 09:55

MOT test number 748644871212

Result ✗ Failed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

Notice Child seat fitted not allowing full inspection of adult belt

MOT #1 2010-08-12 17:16

MOT test number 361904120411

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
31 July 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-09-11
Last registration	2023-08-01
Complete history	See info



Registration #1	2007-09-11	28 mi
Registration #2	2010-08-12	47.497 mi
Registration #3	2011-10-01	56.505 mi
Registration #4	2011-10-01	56.505 mi
Registration #5	2012-10-15	63.992 mi
Registration #6	2013-10-11	72.973 mi
Registration #7	2014-10-17	78.774 mi
Registration #8	2015-05-20	85.277 mi
Registration #9	2016-05-20	91.777 mi
Registration #10	2017-05-20	98.277 mi
Registration #11	2018-05-20	104.777 mi
Registration #12	2019-05-20	111.277 mi
Registration #13	2020-05-20	117.777 mi
Registration #14	2023-08-01	124.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1671 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	BKP 215735