






report date: 2024-03-28

General information

Make	HONDA
Model	INSIGHT IMA HS-T
Colour	Grey
Year of manufacture	2014
Top speed	113 mph
Gearbox	1 speed CVT

Engine & fuel consumption

Power	87 BHP
Max. torque	120 Nm at 4.500 rpm
Engine capacity	1.339 сс
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	62.8 mpg
Consumption extra urban	67.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-23

Pictures 23

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-08
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	11
Total items failed	1

MOT #16	2024-04-04 14:26
MOT test number	471530016081
Result	✓ Passed
Next expiry date	2025-04-08

MOT #15	2024-04-04 11:31
MOT test number	312807611889
Result	× Failed
DANGEROUS Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MAJOR Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
DANGEROUS Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	

MOT #14	2023-04-04 13:06
MOT test number	532844543950
Result	✓ Passed
Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

	MOT #13		2022-04-05 15:57
	MOT test	number	997529921946
ı	Result		✓ Passed
	Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
	Advice	Nearside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

	_
MOT #12	2021-04-09 15:36
MOT test number	946444688980
Result	✓ Passed
MOT #11	2020-10-01 10:53
MOT test number	807920836353
Result	✓ Passed
MOT #10	2020-09-14 10:49
MOT test number	969469246085
Result	✓ Passed
MOT #9	2020-03-19 14:25
MOT test number	161131481259

MOI #9	2020-03-19 14:25
MOT test number	161131481259
Result	✓ Passed

MOT #8	2019-10-07 11:20
MOT test number	894972291834
Result	✓ Passed

MOT #7	2019-10-07 11:20
MOT test number	842007955596
Result	★ Failed
Pass with rectification (1.1.14 (a) (ii))	Front Brake disc in such a condition that it is seriously weakened both side

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #6	2019-04-01 14:29
MOT test number	320813512744
Result	✓ Passed
MOT #5	2018-09-20 11:37
MOT test number	994800672410
Result	✓ Passed
MOT #4	2018-03-22 09:16
MOT test number	392637279802
Result	✓ Passed
Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice Offside Front Shock absorber has a light misting of oil (2.7.3)	

MOT #3	2017-09-14 16:00
MOT test number	543099598916
Result	✓ Passed
MOT #2	2017-03-21 16:42
MOT test number	578994070058
Result	✓ Passed
MOT #1	2017-01-26 15:03
MOT test number	372225715217
Result	✓ Passed
Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)	
Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check

Tax expired: 26 April 2024





Tax status	Expired at 26 April 2024
Days left	2 days too late
MOT expiry date	8 April 2025
Full MOT history	See MOT history

Expires: 8 April 2025

Tax calculation

Vehicle class	59
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

\sim	
()Whar	hictory
Owner	HISLOLY

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

THE STATE OF THE S	
THE STREET STREE	
	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	
Current registration	OK.
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2014-02-01
Last registration	2024-04-04
Complete history	See info



Registration #1	2014-02-01	26 mi
Registration #2	2017-01-26	36.927 mi
Registration #3	2017-03-21	37.436 mi
Registration #4	2017-09-14	53.578 mi
Registration #5	2018-03-22	65.128 mi
Registration #6	2018-09-20	74.759 mi
Registration #7	2019-04-01	84.993 mi
Registration #8	2019-10-07	98.301 mi
Registration #9	2019-10-07	98.301 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		11.777 es
Registration #18		71.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	90%
Children	74%
Pedestrian	76%
Safety systems	86%
Overall rating	84%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1435 mm
Length	4395 mm
Wheel base	2545 mm
Kerb weight	1243 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LDA3 4009332

CarCheck.co.uk page 12/12