



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SE DSG
Colour	Grey
Year of manufacture	2010
Top speed	110 mph
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	85 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg
CO2 emission	135 g/km
CO2 label	E





MOT history

MOT expiry date	2025-04-24
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	16
Total items failed	24

MOT #19	2024-03-28 10:49
MOT test number	236116855270
Result	✓ Passed
Next expiry date	2025-04-24
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #18	2023-04-25 09:37
MOT test number	164053722299
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Play in steering rack inner joint(s)

**MOT #17**

2023-04-24 09:44

MOT test number

208845497742

Result**✗ Failed**

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Central Rear Seat belt not functioning as intended (7.1.2 (c))
- Fail** Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #16

2023-03-04 14:50

MOT test number

866357361382

Result**✗ Failed**

- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Central Rear Seat belt not functioning as intended (7.1.2 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Bumper insecure (6.1.4 (a) (i))

**MOT #15**

2022-02-11 13:00

MOT test number

471004482455

Result

✓ Passed

Advice Nearside front coil spring incorrectly positioned**Advice** Offside Steering arm deformed but serviceable tie rod (2.1.3 (c) (i))**MOT #14**

2022-02-10 12:10

MOT test number

623512833252

Result

✗ Failed

Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Nearside front coil spring incorrectly positioned**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Steering arm deformed but serviceable tie rod (2.1.3 (c) (i))**MOT #13**

2021-01-13 11:28

MOT test number

575342318866

Result

✓ Passed

MOT #12

2020-01-08 14:53

MOT test number

446687316566

Result

✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing age cracking (5.2.3 (d) (ii))

**MOT #11** 2019-01-12 16:29**MOT test number** 359132465192**Result** ✓ Passed**MOT #10** 2019-01-12 10:46**MOT test number** 809342460534**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #9** 2018-01-17 15:05**MOT test number** 255184698136**Result** ✓ Passed**MOT #8** 2018-01-17 15:05**MOT test number** 564842687570**Result** ✗ Failed**Pass with rectification** Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #7** 2017-01-19 13:42**MOT test number** 937442641385**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2016-01-15 15:25**MOT test number** 896444327519**Result** ✓ Passed**MOT #5** 2016-01-15 15:25**MOT test number** 291886961761**Result** ✗ Failed**Pass with rectification** Headlamp aim too low both front (1.8)**MOT #4** 2015-01-21 11:30**MOT test number** 107071425461**Result** ✓ Passed**MOT #3** 2015-01-21 11:30**MOT test number** 137841925022**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**MOT #2** 2014-01-26 10:48**MOT test number** 649446224058**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-12-20 10:28**MOT test number** 896355652342**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
24 April 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-01-18
Last registration	2024-03-28
Complete history	See info



Registration #1	2010-01-18	7 mi
Registration #2	2012-12-20	39.574 mi
Registration #3	2014-01-26	52.508 mi
Registration #4	2015-01-21	55.143 mi
Registration #5	2016-01-15	57.544 mi
Registration #6	2016-01-15	57.544 mi
Registration #7	2017-01-19	60.859 mi
Registration #8	2018-01-17	67.104 mi
Registration #9	2018-01-17	67.104 mi
Registration #10	2019-01-12	74.963 mi
Registration #11	2019-01-12	74.963 mi
Registration #12	2019-01-12	74.963 mi
Registration #13	2019-01-12	74.963 mi
Registration #14	2019-01-12	74.963 mi
Registration #15	2019-01-12	74.963 mi
Registration #16	2019-01-12	74.963 mi
Registration #17	2019-01-12	74.963 mi
Registration #18	2019-01-12	74.963 mi
Registration #19	2019-01-12	74.963 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1104 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CGG 229203