



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-09-25
Pictures	2
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-09-19
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	26
Total items failed	0

MOT #15	2023-09-18 10:52
MOT test number	579590998481
Result	✓ Passed
Next expiry date	2024-09-19
Advice	Front Tyre worn close to legal limit/worn on edge nearside & offside (5.2.3 (e))

MOT #14	2023-09-15 11:28
MOT test number	478057104716
Result	✗ Failed
Advice	Offside Rear Upper side light inop
DANGEROUS	Offside Rear Tyre has ply or cords damaged (5.2.3 (d) (ii))
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))
DANGEROUS	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Advice	Front Tyre worn close to legal limit/worn on edge nearside & offside (5.2.3 (e))

MOT #13	2022-09-20 14:00
MOT test number	986569371293
Result	✓ Passed
Advice	Undertray not fully secure (8.1.1 (b) (i))
Advice	Rear Tyre worn close to legal limit/worn on edge nearside & offside (5.2.3 (e))

**MOT #12**

2022-09-16 13:24

**MOT test number**

745817792350

**Result****✗ Failed**

**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Undertray not fully secure (8.1.1 (b) (i))

**Advice** Rear Tyre worn close to legal limit/worn on edge nearside & offside (5.2.3 (e))

**MAJOR** Front Suspension arm pin or bush excessively worn nearside & offside (5.3.4 (a) (i))

**MOT #11**

2021-09-18 13:12

**MOT test number**

259750820561

**Result****✓ Passed**

**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Rear both side tyres slightly worn low

**Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))

**MOT #10**

2021-09-18 11:20

**MOT test number**

579934475957

**Result****✗ Failed**

**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Rear both side tyres slightly worn low

**MAJOR** Nearside Rear Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))

**Advice** Rear Coil spring corroded both side (5.3.1 (b) (i))

**MAJOR** Offside Rear Anti-roll bar linkage damaged and seriously weakened (5.3.3 (b) (i))

**MOT #9** 2020-12-07 15:33**MOT test number** 376871204215**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8** 2019-12-23 15:27**MOT test number** 672608244782**Result** ✓ Passed**Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**MOT #7** 2019-01-10 13:39**MOT test number** 273016598535**Result** ✓ Passed**MOT #6** 2018-01-12 15:18**MOT test number** 403085287290**Result** ✓ Passed**Advice** Offside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2017-01-24 14:13**MOT test number** 320414236348**Result** ✓ Passed**MOT #4** 2016-02-03 09:55**MOT test number** 178658920567**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit Inner (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit Inner (4.1.E.1)



MOT #3	2015-02-04 12:23
MOT test number	876165535073
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2014-02-24 16:53
MOT test number	726655454071
Result	✓ Passed

MOT #1	2013-04-17 09:34
MOT test number	517427803115
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 January 2025

✓  
**MOT**

**Expires:**  
19 September 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	19 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-22
Last registration	2023-09-18
Complete history	<a href="#">See info</a>



Registration #1	2010-03-22	15 mi
Registration #2	2013-04-17	31.094 mi
Registration #3	2014-02-24	38.178 mi
Registration #4	2015-02-04	45.728 mi
Registration #5	2016-02-03	53.807 mi
Registration #6	2017-01-24	62.548 mi
Registration #7	2018-01-12	70.515 mi
Registration #8	2019-01-10	79.564 mi
Registration #9	2019-12-23	86.501 mi
Registration #10	2020-03-22	91.377 mi
Registration #11	2020-03-22	91.377 mi
Registration #12	2020-03-22	91.377 mi
Registration #13	2020-03-22	91.377 mi
Registration #14	2020-03-22	91.377 mi
Registration #15	2020-03-22	91.377 mi
Registration #16	2020-03-22	91.377 mi
Registration #17	2020-03-22	91.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	1260602