





General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Black
Year of manufacture	2003
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	185 g/km
CO2 label	I







Internet history		
Entry 2		
Date	2022-02-21	
Pictures	0	
Listing price	View report	

source: autotrader.co.uk

Entry 1

Date	2021-10-08
Pictures	20
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2023-10-16
MOT pass rate	72 %
MOT passed	18
Failed MOT tests	7
Total advice items	27
Total items failed	9

MOT #25 2022-10-17 13	
MOT test number	931135326357
Result	✓ Passed
Next expiry date	2023-10-16
Advice Rear Brake disc worn, pit	ted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice Suspension component pin or bush slightly worn osf and nsf subframe (5.3.4 (a) (i))	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

MOT #24	2022-10-17 07:50	
MOT test number	855863117664	
Result	🗙 Failed	
Advice Suspension component pin or bush slightly worn osf and nsf subframe (5.3.4	4 (a) (i))	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		
DANGEROUS Tyre has ply or cords exposed osf and nsf (5.2.3 (d) (ii))		
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))	
DANGEROUS Tyre tread depth below requirements of 1.6mm osf and nsf (5.2.3 (e))	

МОТ #23	2021-10-06 16:14
MOT test number	207127985201
Result	✓ Passed





MOT #22		2020-09-10 14:02
MOT test	number	975445738664
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Exhaust mounting defective (6.1.2 (a))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))	

MOT #21		2020-09-10 09:22
MOT test	number	331893229660
Result		🗙 Failed
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Exhaust mounting defective (6.1.2 (a))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	ı) (ii))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))	
MAJOR Rear fog lamp adversely affected by the operation of another lamp fog light comes on when headlights are switch on (4.5.4 (b))		comes on when

MOT #20		2019-03-27 12:18
MOT test	number	152560299153
Result		🗸 Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #19	2018-03-19 08:29
MOT test number	657629168545
Result	✓ Passed
MOT #18	2018-03-19 08:29
MOT test number	314298066212
Result	× Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #17	2017-03-17 11:42
MOT test number	121993228892
Result	✓ Passed

MOT #2	16	2017-03-09 08:28
MOT te	st number	804311072772
Result		🗙 Failed
Fail	Offside Front coil spring broken (2.4.C.1a)	
Fail	Offside Rear coil spring broken (2.4.C.1a)	
Fail	Nearside Rear coil spring broken (2.4.C.1a)	

MOT #15	2015-09-21 17:02
MOT test number	799366850351
Result	✓ Passed
MOT #14	2015-09-21 17.02

MOT #14		2015-09-21 17:02
MOT test number		683001812652
Result		× Failed
Pass with rectification	Offside Stop lamp not working (1.2.1b)	





MOT #13	2014-10-31 16:42
MOT test number	845734504334
Result	✓ Passed
MOT #12	2013-10-02 10:48
MOT test number	225905473296
Result	✓ Passed
MOT #11	2012-11-05 16:31
MOT test number	906230712352
Result	✓ Passed
MOT #10	2012-11-05 13:02
MOT test number	336720012352
Result	🗙 Failed
Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice N/s rear tyre cracking on tread and sidewall	
FailBrakes imbalanced across an axle (3.7.B.5b)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

МОТ #9	2012-07-16 11:40
MOT test number	228258192166
Result	✓ Passed

МОТ #8	2011-07-28 16:53
MOT test number	266959401295
Result	✓ Passed





MOT #7		2011-07-28 16:53
MOT test number		248879501255
Result		🗙 Failed
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)	
Pass with rectification	Offside Stop lamp not working (1.2.1b)	

MOT #6		2010-09-18 12:09
MOT test	number	664691160274
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #5	2009-09-23 15:53
MOT test number	301436469453
Result	✓ Passed

MOT #4	2008-09-24 11:14
MOT test number	274238968258
Result	✓ Passed

MOT #3	2007-09-03 17:19
MOT test number	922786247265
Result	✓ Passed

MOT #2	2007-05-25 14:08
MOT test number	243645347451
Result	✓ Passed





MOT #1	2006-05-25 17:16
MOT test number	643785346185
Result	✓ Passed



PF03RZZ report date: 2024-03-29

Tax & MOT check

X Untaxed Tax expired: 30 November 2022	X MOT Expired: 16 October 2023
Tax status	Expired at 30 November 2022
Days left	517 days too late
MOT expiry date	16 October 2023
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEED ON
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Date	OLE I
Category	AM
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second sec	

And a second s	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Carrent registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2003-05-30
Last registration	2022-10-17
Complete history	See info



Registration #1	2003-05-30	28 mi
Registration #2	2006-05-25	15.781 mi
Registration #3	2007-05-25	21.729 mi
Registration #4	2007-09-03	23.317 mi
Registration #5	2008-09-24	31.059 mi
Registration #6	2009-09-23	49.753 mi
Registration #7	2010-09-18	67.950 mi
Registration #8	2011-07-28	71.887 mi
Registration #9	2012-07-16	82.658 mi
Registration #10	2012-11-05	84.733 mi
Registration #11	2012-11-05	84.734 mi
Registration #12	2013-10-02	89.696 mi
Registration #13	2014-10-31	95.701 mi
Registration #14	2015-09-21	99.804 mi
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.777 esi
Registration #18		11.777 esi
Registration #19		11.777 esi
Registration #20		11.777 esi
Registration #21		11.777 mi
Registration #22		11.777 esi
Registration #23		11.777 mi
Registration #24		11.117 mi
Registration #25		11.227 mi
Registration #26		11.117 mi
CarCheck.co.uk		page 14/15





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight Width 1724 mm Height 1498 mm Length 4081 mm Wheel base 2508 mm Kerb weight 1385 kg Additional information Fuel tank capacity 55 I **Fuel delivery** Multi-Point Injection

2

2

Number of axles

Number of doors