

Ford



General information

Make	FORD
Model	KUGA ST-LINE TDCI
Colour	Grey
Year of manufacture	2017
Top speed	124 mph
0 - 100 km/h	9.2 seconds
0 - 60 mph	10.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	110 kW / 150 HP / 178 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	57.6 mpg
Consumption combined	54.3 mpg
CO2 emission	134 g/km
CO2 label	E







Internet history	
Entry 2	
Date	2021-07-03
Pictures	0
Listing price	View report
source: cargurus.co.uk	
Entry 1	
Date	2021-07-02
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-01
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	26
Total items failed	0

MOT #5		2023-08-02 13:12
MOT test	number	607659079517
Result		✓ Passed
Next exp	iry date	2024-08-01
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor	Nearside Front Brake hose slightly twisted (1.1.12 (b) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #4		2022-08-01 15:28
MOT test	number	971527697922
Result		✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #3

MOT #3		2022-08-01 13:51
MOT test	number	194754391313
Result		🗙 Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)) (ii))
MAJOR (2.1.3 (g)	Nearside Front Steering rack gaiter missing or no longer prevents the ingress (ii))	of dirt detached





MOT #2		2021-07-09 11:55
MOT test	number	943786519040
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened both	n (1.1.14 (a) (ii))
MOT #1		2020-08-11 10:54
		2020-00-11 10.34
MOT test	number	159621757173
MOT test Result	number	
	number Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1	159621757173 Passed



Tax & MOT check

√ Taxed	√ МОТ
Tax due: 1 February 2025	Expires: 1 August 2024
Tax status	Valid until 1 February
Days left	279
MOT expiry date	1 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	н
First licence fee (12 months)	£ 255,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 645,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Carrent registration	
Plate since	
Exercised considerations	
Carriers registration	
Plate since	





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

In miles
8
2017-08-25
2023-08-02
See info



Registration #1	2017-08-25	16 mi
Registration #2	2020-08-11	41.799 mi
Registration #3		11.777 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.117 esi





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	86%
Pedestrian	70%
Safety systems	100%
Overall rating	88%
Video	see crash video



Dimensions & weight	
Width	2086 mm
Height	1737 mm
Length	4541 mm
Wheel base	2690 mm
Kerb weight	1616 kg
Max. allowed weight	2230 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 12/12