





report date: 2024-03-28

General information

Make	ТОУОТА
Model	AVENSIS D-4D T SPIRIT
Colour	Blue
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	310 Nm at 2.400 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-06-14

Pictures 4

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

MOT history

MOT expiry date	2024-10-28
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	31
Total items failed	11

MOT #14	2023-10-28 11:04
MOT test number	928943082513
Result	✓ Passed
Next expiry date	2024-10-28
Advice Front Suspension arm pin or bush worn but not resulting in excessive movement OSF&NSF lower arm rear bush. (5.3.4 (a) (i))	
Advice Front Headlamp has a product on the lens but not seriously reducing (b))	g light output OSF&NSF (4.1.4

MOT #13	2022-10-29 11:15
MOT test	number 685966809285
Result	✓ Passed
Advice (b))	Front Headlamp has a product on the lens but not seriously reducing light output NSF&OSF (4.1.4
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge Worn on edge (5.2.3 (e))

MOT #12	2021-10-29 16:33
MOT test number	517430359250
Result	✓ Passed

CarCheck.co.uk page 3/14



Pass with rectification

MOT #10

Advice

FD12TFU

report date: 2024-03-28

2021-02-17 10:13

MOT #11

MOT test number

Result

Pass with rectification

Nearside Front Headlamp aim too low (4.1.2 (a))

Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT test number 326551562139

Minor Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Play in steering rack inner joint(s)

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9

MOT test number

309910209579

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #8 2020-02-19 10:49 **MOT** test number 216381979200 Result **X** Failed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Rear Direction indicator incorrect colour (4.4.3 (a)) Fail **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Fail Nearside Headlamp aim too low (4.1.2 (a)) Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Rear Direction indicator incorrect colour (4.4.3 (a)) Fail

MOT #7		2018-06-05 14:02
MOT test	number	173054578244
Result		✓ Passed
Advice	Engine covers and undertrays fitted	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear bumper slightly insecure	
Advice	Offside Rear reflector slightly damaged	

CarCheck.co.uk page 5/14



Advice

Offside Rear bumper slightly insecure

FD12TFU

report date: 2024-03-28

MOT test number

690531029773

Result

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Rear reflector slightly damaged

Advice Engine covers and undertrays fitted

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #5

MOT test number

821750497171

Result

✓ Passed

MOT #4

2017-05-31 14:37

MOT test number

527949505983

Result

✓ Pass with rectification


Windscreen wiper does not clear the windscreen effectively BOTH (8.2.2)

	,
MOT #3	2016-06-20 09:17
MOT test number	163682940539
Result	✓ Passed
MOT #2	2015-06-09 15:16
MOT test number	476570565177
Result	✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-28



CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	28 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 8/14




report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

More info >

Owner history

e mier metery	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	
Current registration	UK UK
Flate since	
Current registration	OK SIE
Plate since	

CarCheck.co.uk page 11/14



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-06-26
Last registration	2023-10-28
Complete history	See info



Registration #1	2012-06-26	19 mi
Registration #2	2015-06-09	28.673 mi
Registration #3	2016-06-20	39.358 mi
Registration #4	2017-05-31	49.923 mi
Registration #5	2017-05-31	49.923 mi
Registration #6	2018-06-05	56.918 mi
Registration #7	2018-06-05	56.918 mi
Registration #8	2020-02-19	74.809 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	86%
Pedestrian	53%
Safety systems	86%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1480 mm
Length	4780 mm
Wheel base	2700 mm
Kerb weight	1635 kg
Max. allowed weight	2130 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 14/1-

Engine number

1AD5645340