



FX65XAB

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT
Colour	White
Year of manufacture	2015
Gearbox	-

Engine & fuel consumption

Engine capacity	2.198 cc
Fuel type	Diesel
CO2 emission	212 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-14
Pictures	19
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-10-15
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	15
Total items failed	10

MOT #8	2023-10-16 10:21
MOT test number	574696332616
Result	✓ Passed
Next expiry date	2024-10-15
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #7** 2023-10-03 15:29**MOT test number** 572181533690**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Obligatory mirror slightly damaged mirror cracked (3.3 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front tyre worn on outer edge
- Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt insecure to rack (2.1.3 (g) (ii))
- Advice** Towball/hitch not fitted at time of test
- Minor** Offside Side repeater lens defective which has no effect on emitted light lens half filled with water (4.4.1 (b) (i))
- Advice** Nearside Front Seat belt slightly damaged (7.1.2 (b) (i))
- Advice** Nearside Rear axle hub seal weeping
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Minor** Trailer electrical socket wiring insulation damaged or deteriorated (4.10 (b) (i))
- Advice** Nearside blind spot mirror missing

MOT #6 2022-09-09 14:05**MOT test number** 237527989231**Result** ✓ Passed

**MOT #5** 2022-08-26 14:40**MOT test number** 827266292800**Result** ✗ Failed

- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Windscreen washer not working (3.5 (a))
- Fail** Nearside Side repeater lens defective such that the emitted light is adversely affected (4.4.1 (b) (ii))
- Fail** Nearside Front Inner Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #4 2021-08-23 13:39**MOT test number** 547503651321**Result** ✓ Passed

- Advice** Nearside side repeater cover broken.
- Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #3 2020-08-28 10:53**MOT test number** 824436011803**Result** ✓ Passed**MOT #2** 2019-08-30 10:42**MOT test number** 823502566733**Result** ✓ Passed



MOT #1	2018-08-23 13:43
MOT test number	267534212709
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
15 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	15 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	FX65XAB
Plate since	2024-03-28
Current registration	FX65XAB
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-09-08
Last registration	2023-10-16
Complete history	See info



Registration #1	2015-09-08	28 mi
Registration #2	2018-08-23	41.469 mi
Registration #3	2019-08-30	55.079 mi
Registration #4	2020-08-28	71.791 mi
Registration #5	2021-08-23	85.838 mi
Registration #6	2022-08-23	99.889 mi
Registration #7	2023-08-23	113.940 mi
Registration #8	2023-08-23	127.991 mi
Registration #9	2023-08-23	142.042 mi
Registration #10	2023-10-16	156.093 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	90%
Pedestrian	48%
Safety systems	71%
Overall rating	76%
Video	see crash video



Additional information

Number of seats	3
Engine number	FS17457