





report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI SE NAV BUSINESS BLUE DRIVE
Colour	Silver
Year of manufacture	2015
Top speed	126 mph
0 - 60 mph	12.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	139 BHP
Max. torque	340 Nm at 1.700 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	50.4 mpg
Consumption extra urban	61.4 mpg
Consumption combined	56.5 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2022-01-22

Pictures 17

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-05-10
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	13
Total items failed	2

MOT #8	2024-04-15 10:50
MOT test number	522955178022
Result	✓ Passed
Next expiry date	2025-05-10
Advice Nearside Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))	

MOT #7	2023-04-29 12:02
MOT test number	755186732314
Result	✓ Passed
MOT #6	2023-04-28 14:43
MOT test number	525394962445
Result	× Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge ON THE LEGAL LI	IMIT. (5.2.3 (e))
Advice Nearside Rear Nail in tyre	
Fail Offside Front Service brake excessively binding (1.2.1 (f))	

CarCheck.co.uk page 3/11



MOT #5 2022-05-11 15:22

MOT test number 571826432008

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2021-06-30 08:07

MOT test number 746134689695

Result
✓ Passed

MOT #3 2020-06-25 07:31

MOT test number 596967343310

Result \rightarrow Passed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2019-07-17 14:54

MOT test number 687881065386

Result \(\sqrt{Passed} \)

Advice Water coolant low

Advice N/s front tyre 2mm

MOT #1 2018-07-06 13:04

MOT test number 210771553568

Result
✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge on inner edge (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	10 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

ET15UML

report date: 2024-03-28

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

More info >

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-07-22
Last registration	2024-04-15
Complete history	See info



Registration #1	2015-07-22	13 mi
Registration #2	2018-07-06	49.069 mi
Registration #3	2019-07-17	59.241 mi
Registration #4	2020-06-25	68.745 mi
Registration #5	2021-06-30	74.026 mi
Registration #6		11.777 es
Registration #6 Registration #7		11.777 ea
-		11.77 m
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4775 mm
Wheel base	2770 mm
Kerb weight	1659 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/

Number of axles 2

Engine number D4FDFU552711