



report date: 2024-03-28

General information

| | |
|---------------------|-----------------|
| Make | VOLVO |
| Model | C30 D3 R-DESIGN |
| Colour | Black |
| Year of manufacture | 2012 |
| Top speed | 130 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 148 BHP |
| Max. torque | 350 Nm at 1.500 rpm |
| Engine capacity | 1.984 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 40.4 mpg |
| Consumption extra urban | 70.6 mpg |
| Consumption combined | 55.4 mpg |
| CO2 emission | 134 g/km |
| CO2 label | E |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-04 |
| Pictures | 7 |
| Listing price | View report |



source: autotrader.co.uk

**MOT history**

| | |
|---------------------------|------------|
| MOT expiry date | 2025-01-18 |
| MOT pass rate | 69 % |
| MOT passed | 9 |
| Failed MOT tests | 4 |
| Total advice items | 21 |
| Total items failed | 4 |

| | |
|-------------------------|--|
| MOT #13 | 2024-01-19 15:36 |
| MOT test number | 824344459096 |
| Result | ✓ Passed |
| Next expiry date | 2025-01-18 |
| Advice | Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e)) |

| | |
|------------------------|--|
| MOT #12 | 2024-01-16 15:30 |
| MOT test number | 801915506485 |
| Result | ✗ Failed |
| Fail | Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) |
| Advice | Front Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e)) |

| | |
|------------------------|---|
| MOT #11 | 2022-11-29 21:07 |
| MOT test number | 147174595326 |
| Result | ✓ Passed |
| Advice | Advice on further look at front and rear brakes and brake discs |
| Advice | Advice keep eye on all tyres |

**MOT #10** 2022-11-29 21:07**MOT test number** 226660159124**Result** ✗ Failed**Advice** Advice on further look at front and rear brakes and brake discs**Pass with rectification** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Advice keep eye on all tyres**MOT #9** 2021-10-19 14:28**MOT test number** 427585564925**Result** ✓ Passed**MOT #8** 2021-01-25 10:30**MOT test number** 776674281640**Result** ✓ Passed**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2021-01-25 10:30**MOT test number** 448267323894**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2019-07-25 08:56**MOT test number** 770524736304**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2018-07-24 12:24**MOT test number** 451936550006**Result** ✓ Passed**MOT #4** 2017-07-29 14:43**MOT test number** 770828088475**Result** ✓ Passed**Advice** Nearside Front Inner edge of tyre bald**Advice** Offside Front Inner edge of tyre bald**MOT #3** 2017-07-29 14:43**MOT test number** 778940051702**Result** ✗ Failed**Advice** Offside Front Inner edge of tyre bald**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front Inner edge of tyre bald



| | |
|-----------------|---|
| MOT #2 | 2016-06-29 13:14 |
| MOT test number | 556279150475 |
| Result | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) |

| | |
|-----------------|--|
| MOT #1 | 2015-06-24 11:41 |
| MOT test number | 925705675116 |
| Result | ✓ Passed |
| Notice | Both front tyres showing wear on edges |



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
18 January 2025

| | |
|------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 18 January 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|---|------------|
| Vehicle class | 49 |
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,299 |
| Auction value | £ 19,299 |
| Average private trade value | £ 19,299 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this VOLVO had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  XX12UBG |
| Plate since | 2024-03-28 |
| Current registration |  XX12UBG |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2012-06-26 |
| Last registration | 2024-01-19 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-06-26 | 29 mi |
| Registration #2 | 2015-06-24 | 26.507 mi |
| Registration #3 | 2016-06-29 | 36.060 mi |
| Registration #4 | 2017-07-29 | 46.201 mi |
| Registration #5 | 2017-07-29 | 46.201 mi |
| Registration #6 | 2018-07-24 | 54.913 mi |
| Registration #7 | 2019-07-25 | 62.964 mi |
| Registration #8 | 2021-01-25 | 70.172 mi |
| Registration #9 | 2022-01-20 | 75.277 mi |
| Registration #10 | 2022-01-20 | 75.277 mi |
| Registration #11 | 2022-01-20 | 75.277 mi |
| Registration #12 | 2022-01-20 | 75.277 mi |
| Registration #13 | 2022-01-20 | 75.277 mi |
| Registration #14 | 2022-01-20 | 75.277 mi |
| Registration #15 | 2022-01-20 | 75.277 mi |

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1770 mm |
| Height | 1454 mm |
| Length | 4476 mm |
| Wheel base | 2640 mm |
| Kerb weight | 1520 kg |
| Max. allowed weight | 2020 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 60 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |

| | |
|------------------------|---------|
| Number of axles | 2 |
| Engine number | 1115610 |