





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	SLK SLK250 CDI BLUEEFFICIENCY AMG SPORT
Colour	Silver
Year of manufacture	2014
Top speed	151 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	150 kW / 204 HP / 204 BHP
Max. torque	500 Nm at 1.600 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	132 g/km
CO2 label	E



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-29


Pictures 27

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1010		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2025-04-25
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	10
Total items failed	6

MOT #9	2024-04-17 09:51
MOT test number	349682115986
Result	✓ Passed
Next expiry date	2025-04-25

MOT #8	2023-04-18 10:59
MOT test number	926282148349
Result	✓ Passed
Advice Under trays fitted	

MOT #7	2023-04-17 09:46
MOT test number	937768844518
Result	X Failed
Fail Offside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of di	irt (5.3.4 (b) (ii))
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Under trays fitted	
Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of	dirt (5.3.4 (b) (ii))
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #6 2022-04-26 14:17

MOT test number 243531451484

MOT #5 2021-09-07 16:08

MOT test number 104492175160

Result

Passed

MOT #4 2021-08-23 08:54

MOT test number 502985772526

Result X Failed

Fail Offside Front Lower Suspension arm pin or bush excessively worn Front bush (5.3.4 (a) (i))

Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt Rear ball joint (5.3.4 (b) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 1.8mm (5.2.3 (e))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front bush (5.3.4 (a) (i))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3 2019-07-19 10:10

MOT test number 363802761361

MOT #2 2018-06-25 11:34

MOT test number 732878111217

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2.2mm (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2.1mm (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1		2017-06-26 08:18
MOT test	number	325617228239
Result		✓ Passed
Advice	Front both tyres cracking round tread	
Advice	Front both tyres worn on inner edges	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How may MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. It report here .	

	More info >
Plate changes	
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	AIS UK
Plate since	
Current registration	UK UK
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-31
Last registration	2024-04-17
Complete history	See info



Registration #1	2014-03-31	24 mi
Registration #2	2017-06-26	17.943 mi
Registration #3	2018-06-25	25.784 mi
Registration #4	2019-07-19	38.129 mi
Registration #5	2021-08-23	51.153 mi
Registration #6	2021-09-07	51.181 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.177 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0295	
50482	
60501	
60566	
60567	
60569	

Dimensions & weight

Width	1810 mm
Height	1301 mm
Length	4134 mm
Wheel base	2430 mm
Kerb weight	1590 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	65198032265025

CarCheck.co.uk page 12/12