



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	FOX URBAN FOX
Colour	Grey
Year of manufacture	2009
Top speed	92 mph
0 - 60 mph	17.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-03
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-09-27
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	10
Total items failed	15

MOT #19	2023-09-21 15:15
MOT test number	925764187418
Result	✓ Passed
Next expiry date	2024-09-27

MOT #18	2022-09-20 15:22
MOT test number	529755880294
Result	✓ Passed

MOT #17	2022-09-20 13:48
MOT test number	484109154798
Result	✗ Failed
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Brake fluid contaminated (1.8 (a))

MOT #16	2021-09-28 08:50
MOT test number	370489907777
Result	✓ Passed

**MOT #15** 2021-09-28 08:50**MOT test number** 909044715876**Result** ✗ Failed**Pass with rectification** Stop lamp(s) all not working (4.3.1 (a) (iii))**MOT #14** 2020-12-01 14:01**MOT test number** 419629025374**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #13** 2020-12-01 10:39**MOT test number** 548834816896**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**MOT #12** 2019-12-11 13:04**MOT test number** 433298664735**Result** ✓ Passed

**MOT #11** 2019-12-11 10:03**MOT test number** 239951075739**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #10** 2018-12-13 12:08**MOT test number** 222304984099**Result** ✓ Passed**MOT #9** 2018-12-13 10:23**MOT test number** 804618992410**Result** ✗ Failed**Fail** Emissions not tested (8.2.1.2 (d))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Fail** Exhaust has a major leak of exhaust gases middle joint and front flexi (6.1.2 (a))**Advice** Front Direction indicator slightly discoloured Both,o/s & n/s (4.4.3 (a))**MOT #8** 2017-12-19 12:58**MOT test number** 824855564650**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #7** 2017-12-19 09:36**MOT test number** 586501962781**Result** ✗ Failed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2016-12-23 09:28**MOT test number** 341498387281**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-11-24 13:23**MOT test number** 735181197220**Result** ✓ Passed**MOT #4** 2015-11-24 11:33**MOT test number** 387343481034**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)**MOT #3** 2014-11-24 09:04**MOT test number** 607048224346**Result** ✓ Passed**MOT #2** 2013-11-21 11:55**MOT test number** 696175023324**Result** ✓ Passed



MOT #1	2012-11-03 10:51
MOT test number	859168302365
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
27 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	27 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>FG59WTN</b>
Plate since	2019-06-29
Current registration	 <b>FG59WTN</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-11-10
Last registration	2023-09-21
Complete history	<a href="#">See info</a>



Registration #1	2009-11-10	10 mi
Registration #2	2012-11-03	25.248 mi
Registration #3	2013-11-21	35.836 mi
Registration #4	2014-11-24	43.942 mi
Registration #5	2015-11-24	52.897 mi
Registration #6	2015-11-24	52.898 mi
Registration #7	2016-12-23	61.263 mi
Registration #8	2017-12-19	68.681 mi
Registration #9	2017-12-19	68.682 mi
Registration #10	2018-12-13	76.350 mi
Registration #11	2018-12-13	76.350 mi
Registration #12	2019-09-20	76.350 mi
Registration #13	2019-09-20	76.350 mi
Registration #14	2019-09-20	76.350 mi
Registration #15	2019-09-20	76.350 mi
Registration #16	2019-09-20	76.350 mi
Registration #17	2019-09-20	76.350 mi
Registration #18	2019-09-20	76.350 mi
Registration #19	2019-09-20	76.350 mi
Registration #20	2019-09-20	76.350 mi
Registration #21	2019-09-20	76.350 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	CHF 004629