





report date: 2024-03-28

General information

Make	ТОУОТА
Model	IQ VVT-I IQ2
Colour	White
Year of manufacture	2009
Top speed	93 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	91 Nm at 4.800 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	57.7 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date	2021-02-05	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/13



BD58WNE report date: 2024-03-28

MOT history

MOT expiry date	2024-10-10
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	22
Total items failed	6

MOT #17	2023-10-11 15:43
MOT test number	168443064413
Result	✓ Passed
Next expiry date	2024-10-10
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #16		2022-07-04 14:21
MOT test	number	388060255847
Result		✓ Passed
Advice (e))	Nearside Rear Outer Tyre worn close to legal limit/worn on edge w	orn to 2mm and perished (5.2.3

MOT #15	2021-04-24 10:48
MOT test number	260993600153
Result	✓ Passed
MOT #14	2021-04-24 10:48
MOT test number	593282261374
Result	★ Failed
Pass with rectification	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2020-09-28 10:20

MOT test number 227379459460

Result ✓ Passed

Advice Front Items removed from driver's view prior to test

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Outer Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system

requires adjustment or repair. (1.2.1 (b) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #12 2019-10-01 14:35

MOT test number 364786674485

Result ✓ Passed

MOT #11 2018-12-10 10:41

MOT test number 363577960495

Result
✓ Passed

MOT #10 2017-12-18 11:54

MOT test number 351491716513

Result
✓ Passed

Advice Offside rear tyre cracking

MOT #9 2016-12-12 09:08

MOT test number 259660543468

Result
✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

 MOT #8
 2016-12-12 09:08

 MOT test number
 544012400998

 Result
 X Failed

Pass with rectification

Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

 MOT #7
 2015-12-11 14:46

 MOT test number
 253794681223

Result ✓ Passed

MOT #6 2014-12-19 09:52

MOT test number 525513954355

MOT #5 2014-12-17 10:59

MOT test number 137641354338

Result X Failed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2014-01-09 16:25

MOT test number 119689704434

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Rear seats/seat belts not tested - seats not in position

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #3 2014-01-09 09:28 726589404085 **MOT** test number Result × Failed Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Notice Rear seats/seat belts not tested - seats not in position Offside Windscreen wiper does not clear the windscreen effectively (8.2.2) Fail **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Fail Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT test number

927227903083

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Both rear seats/seat belts not tested - seats not in position

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)


MOT #1	2012-01-10 14:16
MOT test number	946520112062
Result	✓ Passed

CarCheck.co.uk page 6/13



BD58WNE report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	10 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history	

Owner mistory		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full is)TA

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	UK WEEK	
Plate since		
Current registration	NIEZ AIS UK	
Plate since		
	More info	>

page 10/13 CarCheck.co.uk



report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-01-12
Last registration	2023-10-11
Complete history	See info



Registration #1	2009-01-12	15 mi
Registration #2	2012-01-10	28.349 mi
Registration #3	2013-01-07	35.236 mi
Registration #4	2014-01-09	40.607 mi
Registration #5	2014-01-09	40.609 mi
Registration #6	2014-12-17	45.679 mi
Registration #7	2014-12-19	45.680 mi
Registration #8	2015-12-11	46.747 mi
Registration #9	2016-12-12	48.976 mi
Registration #10	2016-12-12	48.976 mi
Registration #10	2010 12 12	40.570 1111
Registration #11	2010 12 12	40.370 IIII
		40.370 IIII
Registration #11		40.370 IIII
Registration #11 Registration #12		40.370 IIII
Registration #11 Registration #12 Registration #13		40.370 IIII
Registration #11 Registration #12 Registration #13 Registration #14		40.370 IIII
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15		40.370 IIII
Registration #11 Registration #12 Registration #13 Registration #14 Registration #15 Registration #16		40.370 IIII

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	91%
Children	71%
Pedestrian	54%
Safety systems	86%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	1680 mm
Height	1500 mm
Length	2985 mm
Wheel base	2000 mm
Kerb weight	880 kg
Max. allowed weight	1210 kg

Additional information

Fuel tank capacity	32 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 13/13

Number of axles 2

Engine number 1KR0709340