



CITROËN



report date: 2024-03-28

General information

Make	CITROEN
Model	DS3 E-HDI DSTYLE PLUS
Colour	Silver
Year of manufacture	2014
Top speed	113 mph
0 - 60 mph	12.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	95 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-04
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	28
Total items failed	0

MOT #11	2024-04-05 10:54
MOT test number	113346396372
Result	✓ Passed
Next expiry date	2025-04-04
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Broken exhaust mount

MOT #10	2024-04-04 13:51
MOT test number	797923145537
Result	✗ Failed
Advice	Broken exhaust mount
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9	2023-04-05 12:08
MOT test number	110711489370
Result	✓ Passed

**MOT #8** 2023-04-05 09:00**MOT test number** 849316105485**Result** ✗ Failed**Advice** Nearside Front Nail in tyre 205/45/17 nail in inner edge of tread punctured**MAJOR** Front Windscreen wiper does not clear the windscreen effectively aero,s both ineffective (3.4 (b) (ii))**MOT #7** 2022-08-02 14:55**MOT test number** 257863656932**Result** ✓ Passed**Advice** Rear Exhaust mounting defective rearmost exhaust mounting almost corroded all the way through (6.1.2 (a))**Advice** Rear Exhaust mounting defective exhaust mounting above axle excessively corroded and broken away from system (6.1.2 (a))**MOT #6** 2021-04-09 15:31**MOT test number** 436651668773**Result** ✓ Passed

**MOT #5**

2021-04-07 15:31

MOT test number

919538585380

Result**✗ Failed****Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Coolant below minimum**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #4**

2019-06-19 15:20

MOT test number

260247817636

Result**✓ Passed****MOT #3**

2019-06-19 08:33

MOT test number

225713523286

Result**✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))



MOT #2	2018-06-21 10:23
MOT test number	683692771500
Result	✓ Passed
Advice	Rear Registration plate insecure but not likely to fall off (0.1 (a))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2017-06-13 09:20
MOT test number	201124718064
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
4 April 2025

Tax status	Valid until 1 October
Days left	155
MOT expiry date	4 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-07-25
Last registration	2024-04-05
Complete history	See info



Registration #1	2014-07-25	11 mi
Registration #2	2017-06-13	37.112 mi
Registration #3	2018-06-21	54.728 mi
Registration #4	2019-06-19	70.535 mi
Registration #5	2019-06-19	70.535 mi
Registration #6	2019-06-19	70.535 mi
Registration #7	2021-04-07	87.151 mi
Registration #8	2019-06-19	70.535 mi
Registration #9	2019-06-19	70.535 mi
Registration #10	2019-06-19	70.535 mi
Registration #11	2019-06-19	70.535 mi
Registration #12	2019-06-19	70.535 mi
Registration #13	2019-06-19	70.535 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	71%
Pedestrian	35%
Safety systems	83%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1728 mm
Height	1524 mm
Length	3941 mm
Wheel base	2464 mm
Kerb weight	1085 kg
Max. allowed weight	1602 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	JBFM3167254