



General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI DSG
Colour	Black
Year of manufacture	2010
Top speed	128 mph
0 - 60 mph	8.6 seconds
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-27
Pictures	21
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-26
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	30
Total items failed	4

MOT #15	2024-03-27 10:01
MOT test number	224803582325
Result	✓ Passed
Next expiry date	2025-03-26
Advice	Brake disc worn, pitted or scored, but not seriously weakened All discs (1.1.14 (a) (ii))

MOT #14	2023-03-20 17:31
MOT test number	143020251565
Result	✓ Passed
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #13**

2023-03-20 17:31

MOT test number

636829126810

Result**✗ Failed****Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Nearside Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #12**

2022-03-22 08:41

MOT test number

512548728264

Result**✓ Passed****MOT #11**

2021-03-06 10:28

MOT test number

441112961261

Result**✓ Passed****Advice** Items removed from driver's view prior to test Air freshener**MOT #10**

2020-02-25 09:36

MOT test number

663888897827

Result**✓ Passed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2019-03-01 09:45**MOT test number** 362985402175**Result** ✓ Passed**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #8** 2018-02-28 11:20**MOT test number** 735620916777**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2018-02-27 16:16**MOT test number** 581124536645**Result** ✗ Failed**Fail** Offside Side repeater not working (1.4.A.2c)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Front Anti-roll bar ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**MOT #6** 2017-03-09 15:04**MOT test number** 167732324793**Result** ✓ Passed**Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2016-03-22 14:08**MOT test number** 696455961847**Result** ✓ Passed**Advice** Offside Front Lower Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Nearside Front Lower Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**MOT #4** 2016-03-10 10:26**MOT test number** 785166012820**Result** ✗ Failed**Fail** Electronic power steering warning lamp indicates a failure in the system (2.3.8)**Advice** Offside Front Lower Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Nearside Front Lower Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**MOT #3** 2015-03-06 09:22**MOT test number** 379095065022**Result** ✓ Passed**MOT #2** 2014-03-12 15:33**MOT test number** 287791074078**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Mot smoke test not carried out due to smoke meater reading not being able to register**MOT #1** 2013-03-18 10:09**MOT test number** 799167473070**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
26 March 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	26 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-16
Last registration	2024-03-27
Complete history	See info



Registration #1	2010-03-16	18 mi
Registration #2	2013-03-18	45.652 mi
Registration #3	2014-03-12	60.572 mi
Registration #4	2015-03-06	73.648 mi
Registration #5	2016-03-10	82.500 mi
Registration #6	2016-03-22	82.504 mi
Registration #7	2017-03-09	85.829 mi
Registration #8	2018-02-27	89.049 mi
Registration #9	2018-02-28	89.049 mi
Registration #10	2019-03-20	95.377 mi
Registration #11	2020-03-20	95.377 mi
Registration #12	2021-03-20	95.377 mi
Registration #13	2022-03-20	95.377 mi
Registration #14	2023-03-20	95.377 mi
Registration #15	2024-03-20	95.377 mi
Registration #16	2025-03-20	95.377 mi
Registration #17	2026-03-20	95.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1476 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 755957