



report date: 2024-03-28

General information

Make	NISSAN
Model	MICRA VISIA
Colour	Black
Year of manufacture	2014
Top speed	106 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	56.5 mpg
CO2 emission	115 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-04
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-16
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	20
Total items failed	8

MOT #11	2023-07-17 14:20
MOT test number	384635380224
Result	✓ Passed
Next expiry date	2024-07-16
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Screen chips
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #10	2023-07-17 14:20
MOT test number	292446018172
Result	✗ Failed
Advice	Screen chips
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #9	2022-06-15 14:34
MOT test number	454921080937
Result	✓ Passed



MOT #8	2021-06-25 07:29
MOT test number	211460466822
Result	✓ Passed
Advice	Screen chips

MOT #7	2021-06-25 07:29
MOT test number	595678395092
Result	✗ Failed
Advice	Screen chips
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #6	2020-11-14 12:00
MOT test number	929358585068
Result	✓ Passed
Minor	Nearside Windscreen damaged but not adversely affecting driver's view small chip (3.2 (a) (i))
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge Edge worn and on 3.0mm 165 70 R14 (5.2.3 (e))
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge Edge worn and on 2.0mm RECOMMEND REPLACING ASAP 165 70 R14 (5.2.3 (e))
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
Advice	Rear Wiper blade perished

**MOT #5** 2019-11-04 16:51**MOT test number** 274973716862**Result** ✓ Passed

- Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Driver's view Items removed from driver's view prior to test (3.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #4 2018-10-27 13:48**MOT test number** 848862370066**Result** ✓ Passed**MOT #3** 2018-10-27 13:48**MOT test number** 316554347118**Result** ✗ Failed

- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #2 2017-10-31 16:03**MOT test number** 211640520395**Result** ✓ Passed

- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)



MOT #1	2017-10-31 09:19
MOT test number	567015206565
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm inner and outer edges[165/70/r14],81s (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
16 July 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	16 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-10-31
Last registration	2023-07-17
Complete history	See info



Registration #1	2014-10-31	13 mi
Registration #2	2017-10-31	34.644 mi
Registration #3	2017-10-31	34.644 mi
Registration #4	2018-10-27	54.209 mi
Registration #5	2018-10-27	54.209 mi
Registration #6	2019-11-04	75.504 mi
Registration #7	2020-11-14	85.523 mi
Registration #8	2020-11-14	85.523 mi
Registration #9	2020-11-14	85.523 mi
Registration #10	2020-11-14	85.523 mi
Registration #11	2020-11-14	85.523 mi
Registration #12	2020-11-14	85.523 mi
Registration #13	2020-11-14	85.523 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	79%
Pedestrian	58%
Safety systems	57%
Overall rating	75%
Video	see crash video



Dimensions & weight

Width	1665 mm
Height	1520 mm
Length	3825 mm
Wheel base	2450 mm
Kerb weight	925 kg
Max. allowed weight	1425 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number

780147B