





report date: 2024-03-28

## General information

Make	HONDA
Model	HR-V I-VTEC SE
Colour	Black
Year of manufacture	2017
Top speed	116 mph
0 - 60 mph	10.9 seconds
Gearbox	1 speed CVT

## Engine & fuel consumption

Power	129 BHP
Max. torque	155 Nm at 4.600 rpm
Engine capacity	1.498 сс
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	52.3 mpg
CO2 emission	125 g/km
CO2 label	D



CarCheck.co.uk page 1/12



## Internet history

#### Entry 2

Date 2022-01-11

Pictures 30

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-11-10

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2025-01-11
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	15
Total items failed	2

MOT #8	2023-12-27 11:23
MOT test number	753944717041
Result	✓ Passed
Next expiry date	2025-01-11

MOT #7	2022-12-29 14:14
MOT test number	393634371812
Result	<b>√</b> Passed

MOT #6		2022-12-29 11:23
MOT test	number	318057620190
Result		<b>X</b> Failed
MAJOR	Offside Front Road wheel fixing missing (5.2.1 (a) (i))	

MOT #5		2022-01-12 09:53
MOT test	number	616822998735
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing tyre cracked slight	tly (5.2.3 (d) (ii))
Advice distorted (	Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracked and 5.2.3 (d) (ii))	d tread slightly

CarCheck.co.uk page 3/12



MOT #4 2022-01-12 09:53

**MOT test number** 915845280226

Result X Failed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracked and tread slightly distorted (5.2.3 (d) (ii))

**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing tyre cracked slightly (5.2.3 (d) (ii))

**Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a))

MOT #3 2021-04-22 09:44

**MOT test number** 417226380773

Result \( \sqrt{Passed} \)

MOT #2 2021-04-19 12:23

**MOT test number** 589954686585

Result X Failed

**MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))

**MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))

CarCheck.co.uk page 4/12



MOT #1 2020-03-05 14:25

**MOT test number** 505007245675

Result

Advice Items removed from driver's view prior to test

Advice Under trays fitted

Advice Offside Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	11 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	history
OWITCH	IIIJCOI y

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA		
have? Check it in the premium report and see all owner registrations. Download the full r		^
THE PARTY OF THE P		
***************************************		
********		
***************************************		
	More info	
	More into	/
Plate changes		
See in this check if this HONDA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-03-02
Last registration	2023-12-27
Complete history	See info



Registration #1	2017-03-02	12 mi
Registration #2	2020-03-05	29.637 mi
Registration #3	2021-04-19	31.006 mi
Registration #4	2021-04-22	31.006 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	86%
Children	79%
Pedestrian	72%
Safety systems	71%
Overall rating	79%
Video	see crash video



# Dimensions & weight

Width	1772 mm
Height	1605 mm
Length	4294 mm
Wheel base	2610 mm
Kerb weight	1322 kg
Max. allowed weight	1790 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L15B41047425

CarCheck.co.uk page 12/12