





report date: 2024-03-28

## General information

Make	MASERATI
Model	GHIBLI DV6
Colour	Grey
Year of manufacture	2016
Top speed	155 mph
Gearbox	8 speed automatic

# Engine & fuel consumption

Power	275 BHP
Max. torque	600 Nm at 2.600 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

-		-		1
п	L	ΓV	,	т.

entry 1	
Date	2021-09-11
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_			
MO	1	hic	to	r\/
				ıv.
				. ,

MOT expiry date	2024-09-30
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	18
Total items failed	1

MOT #6	2023-09-30 11:32
MOT test number	439713520006
Result	✓ Passed
Next expiry date	2024-09-30

MOT #5		2022-10-01 10:53
MOT test	number	746721548798
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2021-09-13 16:00
MOT test number	253224613273
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT #3** 2020-06-26 14:01

**MOT test number** 321782119899

Result Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 285/35/20 (5.2.3 (e))

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 285/35/20 (5.2.3 (e))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2020-06-26 10:07

MOT test number 541925834717

Result × Failed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 285/35/20 (5.2.3 (e))

Minor Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 285/35/20 (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #1		2019-03-20 10:59
MOT test	number	635626688781
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 5/12



report date: 2024-03-28

#### Tax & MOT check

Tax expired: 12 March 2024



Expires: 30 September 2024

**✓** MOT

Tax statusExpired at 12 March 2024Days left48 days too lateMOT expiry date30 September 2024Full MOT historySee MOT history

#### Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

### Damage history


Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Category

**Type** 



#### Extra MASERATI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

# Owner history

For how long did the current and previous owner(s) have this MASERATI? How many own MASERATI have? Check it in the premium report and see all owner registrations. Downloahere.	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MASERATI had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NIE.
Plate since	

CarCheck.co.uk page 9/12



report date: 2024-03-28

#### Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MASERATI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-03-30
Last registration	2023-09-30
Complete history	See info



Registration #1	2016-03-30	29 mi
Registration #2	2019-03-20	66.568 mi
Registration #3	2020-06-26	79.119 mi
Registration #4	2020-06-26	79.199 mi
Registration #5		0.77 ss
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

# Safety ratings

NCAP rating	****
Adult	95%
Children	79%
Pedestrian	74%
Safety systems	81%
Overall rating	86%
Video	see crash video



# Dimensions & weight

Width	1945 mm
Height	1455 mm
Length	4971 mm
Wheel base	2998 mm
Kerb weight	1950 kg
Max. allowed weight	2500 kg

# Additional information

Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	053945

CarCheck.co.uk page 12/12