



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 D S
Colour	Silver
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	57.6 mpg
Consumption combined	47.1 mpg
CO2 emission	158 g/km
CO2 label	G






Internet history

Entry 2

Date	2023-02-11
Pictures	31
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-03-12
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-16
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	38
Total items failed	14

MOT #19	2024-04-12 14:10
MOT test number	252880195664
Result	✓ Passed
Next expiry date	2025-04-16

MOT #18	2023-04-17 15:11
MOT test number	904638882918
Result	✓ Passed

MOT #17	2023-04-11 15:12
MOT test number	620528421718
Result	✗ Failed

- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #16**

2021-10-26 14:15

MOT test number

220453979456

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both 2.3mm (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated weeping around clip (6.1.7 (g) (i))
- Advice** Rear Direction indicator slightly discoloured both (4.4.3 (a))

MOT #15

2021-10-26 11:07

MOT test number

498990820740

Result

✗ Failed

- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Direction indicator slightly discoloured both (4.4.3 (a))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated weeping around clip (6.1.7 (g) (i))
- Fail** Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both 2.3mm (5.2.3 (e))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #14**

2020-10-30 16:05

MOT test number

538057076623

Result

✓ Passed

Advice Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Engine covers and under shields fitted**MOT #13**

2019-10-30 16:02

MOT test number

115274042484

Result

✓ Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing Perishing sidewall (5.2.3 (d) (ii))**MOT #12**

2019-10-29 13:55

MOT test number

844147271312

Result

✗ Failed

Advice Offside Rear Nail in tyre**Fail** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Boot has hole in it (6.1.7 (g) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing Perishing sidewall (5.2.3 (d) (ii))**Minor** Offside Rear Tyre obviously under inflated (5.2.3 (l))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11**

2018-11-01 10:34

MOT test number

239984243187

Result

✓ Passed

Minor Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #10** 2017-11-02 13:19**MOT test number** 188929671128**Result** ✓ Passed**MOT #9** 2017-11-02 11:52**MOT test number** 449379943264**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm Tyre stepping out of shape (4.1.E.1)**Advice** Nearside Rear Tyre has cut in tread**MOT #8** 2016-10-18 16:08**MOT test number** 767478235087**Result** ✓ Passed**Advice** UNDERSHEILDS FITTED**Advice** ENGINE COVERS FITTED**MOT #7** 2016-10-18 16:08**MOT test number** 225281129576**Result** ✗ Failed**Advice** UNDERSHEILDS FITTED**Advice** ENGINE COVERS FITTED**Pass with rectification** Headlamp aim too high BOTH (1.8)

**MOT #6** 2016-08-23 10:16**MOT test number** 968248268395**Result** ✗ Failed**Fail** Nearside Front Body has a sharp edge caused by damage (6.1.C.1)**Fail** Nearside Front Headlamp aim too high (1.8)**Advice** Under trays fitted**MOT #5** 2015-08-18 10:55**MOT test number** 326890935223**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2015-08-18 10:55**MOT test number** 995870235291**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2014-08-12 11:04**MOT test number** 289054524292**Result** ✓ Passed**Notice** Advise sill and engine covers fitted**Notice** Advise both front tyres worn on inner edges



MOT #2	2013-08-30 08:16
MOT test number	278192443206
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Nail in rear tyre
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2012-08-31 10:25
MOT test number	519564842237
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
16 April 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	16 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-01
Last registration	2024-04-12
Complete history	See info



Registration #1	2009-09-01	11 mi
Registration #2	2012-08-31	26.963 mi
Registration #3	2013-08-30	31.402 mi
Registration #4	2014-08-12	34.951 mi
Registration #5	2015-08-18	38.702 mi
Registration #6	2016-08-23	42.355 mi
Registration #7	2016-10-18	42.357 mi
Registration #8	2016-10-18	42.357 mi
Registration #9	2017-11-02	45.524 mi
Registration #10	2017-11-02	45.524 mi
Registration #11	2018-11-01	48.939 mi
Registration #12	2019-05-29	51.377 mi
Registration #13	2019-05-29	51.377 mi
Registration #14	2019-05-29	51.377 mi
Registration #15	2019-05-29	51.377 mi
Registration #16	2019-05-29	51.377 mi
Registration #17	2019-05-29	51.377 mi
Registration #18	2019-05-29	51.377 mi
Registration #19	2019-05-29	51.377 mi
Registration #20	2019-05-29	51.377 mi
Registration #21	2019-05-29	51.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1715 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	623857
---------------	--------