





report date: 2024-03-29

General information

Make	MINI
Model	COOPER
Colour	Silver
Year of manufacture	2018
Top speed	129 mph
0 - 60 mph	8.1 seconds
Gearbox	7 speed Dual Clutch

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 4.200 rpm
Engine capacity	1.499 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/12



Internet history

Entry 3

Date 2021-09-04

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date	2021-07-28
------	------------

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-07-27	

Pictures 21

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-20
MOT pass rate	50 %
MOT passed	4
Failed MOT tests	4
Total advice items	13
Total items failed	9

MOT #8		2024-04-08 09:49
MOT test	number	855380129337
Result		✓ Passed
Next expi	ry date	2025-04-20
Advice	Nearside Front Tyre wall perished and severely worn on outer edge of tread	
Advice	Nearside Rear Tyre wall perished	
Advice	Offside Front Tyre wall cut	

MOT #7	2024-04-08 09:38
MOT test number	902455815755
Result	× Failed
Advice Nearside Front Tyre wall perished and severely worn on outer edge of tread	
Advice Nearside Rear Tyre wall perished	
Fail Central Rear Seat belt buckle missing (7.1.2 (d))	
Advice Offside Front Tyre wall cut	

CarCheck.co.uk page 3/12



MOT #6

MOT test number

829998228713

Result

Advice Offside Rear Nail in tyre Repairable

Advice Nearside Rear Nail in tyre Repairable

MOT #5 2023-03-27 10:12 **MOT** test number 126092441595 Result × Failed **Pass with rectification** Offside Headlamp aim too high (4.1.2 (a)) Advice Offside Rear Nail in tyre Repairable **Pass with rectification** Nearside Headlamp aim too high (4.1.2 (a)) Fail Nearside Front Tyre has a lump, caused by separation or partial failure of its structure Out of shape (5.2.3 (d) (ii)) **Advice** Nearside Rear Nail in tyre Repairable Offside Front Tyre wall cut and perished. Worn on inner and outer edge of tread **Advice**

MOT #4

MOT test number

198522489929

Result

✓ Passed

MOT test number

Result

Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

CarCheck.co.uk page 4/12



MOT #2 2021-05-11 10:34

MOT test number 512278844614

Result ✓ Passed

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords SIDE WALL (5.2.3 (d) (i))

MOT #1 2021-05-11 10:34

MOT test number 625704974558

Result X Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords SIDE WALL (5.2.3 (d) (i))

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b)

(ii))

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	20 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2018-05-31
Last registration	2024-04-08
Complete history	See info



Registration #1	2018-05-31	9 mi
Registration #2	2021-05-11	29.794 mi
Registration #3	2021-05-11	29.794 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		71,777 es
Registration #11		77.777 es
Registration #12		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1425 mm
Length	3982 mm
Wheel base	2567 mm
Kerb weight	1250 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	40 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	2/12

Number of axles 2

Engine number F802H803