





report date: 2024-03-29

# General information

Make	FORD
Model	C-MAX TITANIUM
Colour	Black
Year of manufacture	2009
Top speed	121 mph
0 - 60 mph	9.2 seconds
Gearbox	4 speed automatic

# Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/14



report date: 2024-03-29

# Internet history

# Entry 2

Date 2022-01-31

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2022-01-11

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-24
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	27
Total items failed	8

MOT #16	2023-11-06 11:07
MOT test number	667373801362
Result	✓ Passed
Next expiry date	2024-11-24

MOT #15	2022-10-31 13:16
MOT test number	410310122457
Result	<b>✓</b> Passed

MOT #14		2021-11-09 11:24
MOT test	number	940984647920
Result		✓ Passed
Advice	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

**MOT #13** 2021-11-08 13:48

**MOT test number** 347589450788

**Result** X Failed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened worn and corroded (1.1.14 (a) (ii))

Fail Offside Front Headlamp aim too high (4.1.2 (a))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened marked and corroded (1.1.14 (a) (ii))

Fail Offside Front Service brake excessively binding (1.2.1 (f))

**MOT #12** 2020-11-20 14:41

**MOT test number** 686771879692

Result 

Passed

**MOT #11** 2020-11-20 10:11

**MOT test number** 325495600927

**Result** X Failed

Advice Nearside Front tyre wearing inner edge

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Advice** Rear exhaust hanger broken

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Front tyre wearing inner and outer edge

**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #10		2019-11-25 10:47
MOT test	number	179891562712
Result		✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #9	2018-11-20 11:21
MOT test number	550423064375
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #8		2017-11-16 16:06
MOT test	number	452006083659
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

CarCheck.co.uk page 5/14



Fail

PE59XRV

report date: 2024-03-29

**MOT #7** 2017-11-16 11:02 **MOT** test number 167857027243 Result × Failed **Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Offside Stop lamp not working (1.2.1b) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Rear Brake pad(s) wearing thin (3.5.1g) Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #6

MOT test number

Result

Advice Childs seat fitted not allowing full inspection of seat belts.

Offside Front Tyre has ply or cords exposed (4.1.D.1b)

MOT test number

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

2016-11-10 11:07

541707028455

X Failed

Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #4

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #3	2014-11-17 11:07
MOT test number	155141224331
Result	✓ Passed
Notice Child seat fitted not allowing full inspection of adult belt	

MOT #2		2013-11-18 10:45
MOT test	number	878352423385
Result		✓ Passed
Notice	Under-trays fitted obscuring some underside components	
Notice	Child seat fitted not allowing full inspection of adult belt	
Notice	Engine covers fitted obscuring some components in the engine bay	

MOT #1	2012-10-01 14:11
MOT test number	918625672206
Result	<b>✓</b> Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	24 November 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

## Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



PE59XRV report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

$\overline{}$						
( )	M/n	er	hι	ct	'n	r٧
$\sim$	4 V I I	L L	ш	Ju	·U	ιy

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>k</u>	
HARMAN CONTRACTOR CONT	
************	
***************************************	
***************************************	
	More info >
Plate changes	
Coo in this shook if this FORD had different number plates	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	OK NEW
Plate since	
Current registration	UK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

## Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-10
Last registration	2023-11-06
Complete history	See info



Registration #1	2009-11-10	28 mi
Registration #2	2012-10-01	8.495 mi
Registration #3	2013-11-18	13.160 mi
Registration #4	2014-11-17	19.402 mi
Registration #5	2015-11-06	30.317 mi
Registration #6	2016-11-10	42.965 mi
Registration #7	2016-11-10	42.965 mi
Registration #8	2017-11-16	50.158 mi
Registration #9	2017-11-16	50.158 mi
Registration #10	2018-11-20	57.092 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		11.777 esi
Registration #18		11.777 es
Registration #19		11.177 es

More info >

CarCheck.co.uk page 13/14



PE59XRV report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1840 mm
Height	1497 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1326 kg
Max. allowed weight	1905 kg

# Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/1

Number of axles 2

**Engine number** 9B33524