



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Silver
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-08-07
Pictures	49
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-09
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #9	2023-05-10 09:01
MOT test number	665683000011
Result	✓ Passed
Next expiry date	2024-05-09
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8** 2023-05-09 07:52**MOT test number** 764826354058**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Items removed from driver's view prior to test**DANGEROUS** Nearside Front Tyre has ply or cords exposed cracked inner edge showing cords (5.2.3 (d) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #7** 2022-03-23 10:02**MOT test number** 924258247094**Result** ✓ Passed**MOT #6** 2021-03-11 10:03**MOT test number** 414356996586**Result** ✓ Passed**MOT #5** 2020-03-03 09:53**MOT test number** 189134133032**Result** ✓ Passed**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement TRAILING ARM BUSH SPLIT BUT NO EXCESSIVE MOVEMENT OBSERVED (5.3.4 (a) (i))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement TRAILING ARM BUSH SPLIT BUT NO EXCESSIVE MOVEMENT OBSERVED (5.3.4 (a) (i))



MOT #4	2019-03-11 11:23
MOT test number	155308634872
Result	✓ Passed
MOT #3	2018-03-05 09:10
MOT test number	594378134534
Result	✓ Passed
MOT #2	2017-03-06 09:54
MOT test number	745759038084
Result	✓ Passed
MOT #1	2016-03-23 12:20
MOT test number	361484032441
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 May 2024

Tax status	Valid until 1 April
Days left	338
MOT expiry date	9 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	SA13XCM
Plate since	2019-03-28
Current registration	SA13XCM
Plate since	2019-03-28

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-03-27
Last registration	2023-05-10
Complete history	See info



Registration #1	2013-03-27	26 mi
Registration #2	2016-03-23	18.930 mi
Registration #3	2017-03-06	29.587 mi
Registration #4	2018-03-05	41.965 mi
Registration #5	2019-03-11	52.293 mi
Registration #6	2020-03-03	57.375 mi
Registration #7	2020-05-20	58.277 mi
Registration #8	2020-05-20	58.277 mi
Registration #9	2020-05-20	58.277 mi
Registration #10	2020-05-20	58.277 mi
Registration #11	2020-05-20	58.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ