





report date: 2024-03-28

General information

Make	AUDI
Model	Q7 TDI QUATTRO S LINE
Colour	Blue
Year of manufacture	2008
Top speed	134 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	550 Nm at 1.500 rpm
Engine capacity	2.967 сс
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.8 mpg
CO2 emission	260 g/km
CO2 label	М



CarCheck.co.uk page 1/13



Internet history

Entry 2

Date 2021-09-09

Pictures 46

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-09-09
Pictures	52

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-10-01
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	20
Total items failed	5

MOT #16	2023-09-16 11:51
MOT test number	749351858356
Result	✓ Passed
Next expiry date	2024-10-01

MOT #15		2022-09-30 15:08
MOT test	number	681589236985
Result		✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



MOT #14 2022-09-20 15:25

MOT test number 640352847182

Result X Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Exhaust diesel particulate filter shows evidence of tampering. (8.2.2.1 (c))

MOT #13 2021-10-02 12:59

MOT test number 124444857993

Result ✓ Passed

MOT #12 2021-03-01 12:50

MOT test number 304758823174

Result \(\sqrt{Passed} \)

Advice Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

MOT #11 2020-01-27 13:37

MOT test number 641062457627

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/13



R31TUR

report date: 2024-03-28

MOT #10	2019-05-16 13:15
MOT test number	155924280594
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #9		2018-01-30 12:34
MOT test number		669162616658
Result		✓ Passed
MOT #8		2018-01-30 12:34
MOT test number		428750545895
Result		× Failed
Pass with rectification	Offside Rear position lamp(s) not working (1.1.A.3b)	

MOT #7		2016-07-15 12:27
MOT test number		443137220576
Result		✓ Passed
MOT #6		2016-07-15 12:27
MOT test number		837850062793
Result		X Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)	

CarCheck.co.uk page 5/13



MOT #5 2015-07-10 14:59

MOT test number 835711895179

Notice All four tyres close to limit

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice Engine management lamp on

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4 2014-07-02 10:59

MOT test number 215803584402

Result \(\sqrt{Passed} \)

Notice Offside rear light in bumper broken,not showing a white light

Advice Offside Front Upper Suspension arm has slight play in a ball joint (2.4.G.2)

Notice EML light on

MOT #3 2012-11-28 13:17

MOT test number 358453132354

Result
✓ Passed

MOT #2 2011-12-01 13:27

MOT test number 277165431343

MOT #1 2011-12-01 13:27

MOT test number 805425431312

Result X Failed

Pass with rectification Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	1 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



R31TUR

report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this AUDI? How many owners d Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	AIR NE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-01
Last registration	2023-09-16
Complete history	See info



Registration #1	2008-09-01	14 mi
Registration #2	2011-12-01	29.418 mi
Registration #3	2012-11-28	43.360 mi
Registration #4	2014-07-02	69.320 mi
Registration #5	2015-07-10	83.880 mi
Registration #6	2016-07-15	92.634 mi
Registration #7	2016-07-15	92.634 mi
Registration #8	2018-01-30	101.708 mi
Registration #9	2018-01-30	101.708 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		11.777 es
Registration #18		11.777 mg

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1983 mm
Height	1737 mm
Length	5086 mm
Wheel base	3002 mm
Kerb weight	2325 kg
Max. allowed weight	3120 kg

Additional information

Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles 2

Engine number CAS 025689