



General information

|                     |                             |
|---------------------|-----------------------------|
| Make                | VOLKSWAGEN                  |
| Model               | TOURAN MATCH TDI BLUEMOTION |
| Colour              | Silver                      |
| Year of manufacture | 2010                        |
| Top speed           | 113 mph                     |
| 0 - 60 mph          | 13.0 seconds                |
| Gearbox             | 6 speed Manual              |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 105 BHP             |
| Max. torque             | 250 Nm at 1.900 rpm |
| Engine capacity         | 1.896 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 40.4 mpg            |
| Consumption extra urban | 60.1 mpg            |
| Consumption combined    | 52.3 mpg            |
| CO2 emission            | 144 g/km            |
| CO2 label               | F                   |





## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2021-03-19 |
| MOT pass rate      | 60 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 6          |
| Total advice items | 45         |
| Total items failed | 15         |

MOT #15 2020-03-09 12:53

MOT test number 542239038248

Result ✓ Passed

Next expiry date 2021-03-19

**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**Advice** Coolant leak

**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))

**Advice** Tyre worn close to legal limit/worn on edge Both fronts worn inner edge (5.2.3 (e))

**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #14**

2020-03-05 15:55

**MOT test number**

445218733487

**Result****✗ Failed**

- Advice** Coolant leak
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Tyre worn close to legal limit/worn on edge Both fronts worn inner edge (5.2.3 (e))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Fail** Offside Front Suspension arm pin or bush excessively worn Front bush (5.3.4 (a) (i))
- Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #13**

2019-03-20 16:36

**MOT test number**

776947296119

**Result****✓ Passed**

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Accident damage repair carried out to nearside outer sill and front door aperture
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Auxiliary belt drive noisy

**MOT #12**

2019-03-18 17:48

**MOT test number**

284676390375

**Result****✗ Failed****Advice**

Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

**Minor**

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Auxiliary belt drive noisy

**Advice**

Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

**Advice**

Accident damage repair carried out to nearside outer sill and front door aperture

**Fail**

Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Fail**

Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**Advice**

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**Fail**

Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #11**

2017-10-03 10:20

**MOT test number**

435162230349

**Result****✓ Passed****Advice**

Offside Front Slight free play at wheel

**Advice**

Oil leak In engine bay

**MOT #10**

2017-09-28 09:25

**MOT test number**

757370860771

**Result****✗ Failed**

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Fail** Nearside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Advice** Offside Rear Tyre worn on inner edge
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Oil leak In engine bay
- Advice** Offside Front Suspension arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Rear Tyre worn in inner edge
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Slight free play at wheel

**MOT #9**

2017-02-23 08:45

**MOT test number**

367547678681

**Result****✓ Passed**

- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside outer sill has poorly repaired accident damage

**MOT #8**

2017-02-22 13:36

**MOT test number**

131613422461

**Result**

✗ Failed

**Fail**

Nearside Registration plate lamp not working (1.1.C.1d)

**Fail**

Nearside Front Suspension arm has excessive play in a pin/bush (2.4.G.2)

**Fail**

Nearside Rear Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement (2.4.G.2)

**Advice**

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail**

Exhaust emits an excessive level of metered smoke (7.4.B.3a)

**Advice**

Nearside outer sill has poorly repaired accident damage

**Advice**

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #7**

2016-03-19 10:51

**MOT test number**

451788973297

**Result**

✓ Passed

**Advice**

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice**

Nearside Front Tyre worn close to the legal limit 205/55/16 1.6mm (4.1.E.1)

**Advice**

Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #6**

2015-03-19 13:55

**MOT test number**

139148975438

**Result**

✓ Passed

**MOT #5**

2014-10-29 16:29

**MOT test number**

799632304359

**Result**

✓ Passed

**MOT #4** 2014-10-28 09:10**MOT test number** 485081204495**Result** ✗ Failed**Notice** O/s/f mirror insecure**Fail** Offside Front Side repeater not working (1.4.A.2c)**MOT #3** 2014-02-25 10:35**MOT test number** 409226054073**Result** ✓ Passed**MOT #2** 2014-02-25 10:13**MOT test number** 725006554068**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #1** 2013-03-20 12:46**MOT test number** 126039773482**Result** ✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
30 October 2020

✕  
MOT

Expired:  
19 March 2021

Tax status

Expired at 30 October 2020

Days left

1277 days too late

MOT expiry date

19 March 2021

Full MOT history

[See MOT history](#)

Tax calculation

|   |            |
|---|------------|
| Vehicle class                           | 49         |
| Band                                    | F          |
| Single payment (12 months)              | £ 200,00,- |
| Single six month payment                | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |   |
|----------------------|---|
| Number of plates     | 7   |
| Current registration |  ***** |
| Plate since          | 2019-06-29  |
| Current registration |  ***** |
| Plate since          | 2019-06-29  |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 16                       |
| First mileage registration | 2010-04-01               |
| Last registration          | 2020-03-09               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2010-04-01 | 29 mi      |
| Registration #2  | 2013-03-20 | 55.143 mi  |
| Registration #3  | 2014-02-25 | 73.415 mi  |
| Registration #4  | 2014-02-25 | 73.415 mi  |
| Registration #5  | 2014-10-28 | 81.157 mi  |
| Registration #6  | 2014-10-29 | 81.157 mi  |
| Registration #7  | 2015-03-19 | 81.180 mi  |
| Registration #8  | 2016-03-19 | 141.928 mi |
| Registration #9  | 2016-03-20 | 141.928 mi |
| Registration #10 | 2016-03-20 | 141.928 mi |
| Registration #11 | 2016-03-20 | 141.928 mi |
| Registration #12 | 2016-03-20 | 141.928 mi |
| Registration #13 | 2016-03-20 | 141.928 mi |
| Registration #14 | 2016-03-20 | 141.928 mi |
| Registration #15 | 2016-03-20 | 141.928 mi |
| Registration #16 | 2016-03-20 | 141.928 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1794 mm |
| Height              | 1635 mm |
| Length              | 4407 mm |
| Wheel base          | 2678 mm |
| Kerb weight         | 1528 kg |
| Max. allowed weight | 2190 kg |

Additional information

|                 |                  |
|-----------------|------------------|
| Fuel delivery   | Direct Injection |
| Number of doors | 5                |
| Number of seats | 7                |

---

**Number of axles**

2

**Engine number**

BLS C28630

---