



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Red
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-05-21
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

**MOT history**

<b>MOT expiry date</b>	2024-06-07
<b>MOT pass rate</b>	79 %
<b>MOT passed</b>	11
<b>Failed MOT tests</b>	3
<b>Total advice items</b>	38
<b>Total items failed</b>	4

<b>MOT #14</b>	2023-06-05 09:01
<b>MOT test number</b>	151216921644
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-06-07
<b>Advice</b>	Oil leak, but not excessive Diff seals (8.4.1 (a) (i))

<b>MOT #13</b>	2023-06-02 10:40
<b>MOT test number</b>	192187231756
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
<b>Fail</b>	Front Brake disc significantly and obviously worn inner surfaces (1.1.14 (a) (i))
<b>Advice</b>	Oil leak, but not excessive Diff seals (8.4.1 (a) (i))

<b>MOT #12</b>	2022-06-06 10:03
<b>MOT test number</b>	737310329368
<b>Result</b>	✓ Passed

**MOT #11**

2021-06-08 10:10

**MOT test number**

993588443191

**Result**

✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust silencer slightly loose (8.1.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Nail in tyre
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #10**

2020-09-09 16:16

**MOT test number**

796013169051

**Result**

✓ Passed

- Advice** Exhaust system corroded
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #9**

2019-09-19 11:21

**MOT test number**

636871141847

**Result**

✓ Passed

- Advice** Front exhaust flexi pipe slightly deteriorated
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Rear exhaust slightly deteriorated (outer skin)
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

**MOT #8**

2018-09-12 11:17

**MOT test number**

340790158896

**Result**

✓ Passed

- Advice** Offside Rear Lower Shock absorbers has slight external damage to the casing casing corroded (5.3.2 (b))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Lower Shock absorbers has slight external damage to the casing casing corroded (5.3.2 (b))
- Advice** Rear exhaust casing slightly deteriorated
- Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #7**

2017-09-28 09:47

**MOT test number**

231532475875

**Result**

✓ Passed

- Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Nearside Front coil spring corroded (2.4.C.1b)
- Advice** Exhaust system corroded
- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Gearbox oil leak

**MOT #6** 2017-09-27 11:23**MOT test number** 137619710702**Result** ✗ Failed

- Advice** Offside Rear coil spring corroded (2.4.C.1b)
- Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Exhaust system corroded
- Fail** Offside Front coil spring broken (2.4.C.1a)
- Advice** Nearside Rear coil spring corroded (2.4.C.1b)
- Advice** Nearside Rear Shock absorber has slight corrosion to the casing (2.7.2a)
- Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice** Gearbox oil leak
- Advice** Nearside Front coil spring corroded (2.4.C.1b)

**MOT #5** 2016-09-19 10:42**MOT test number** 751531964342**Result** ✓ Passed**MOT #4** 2015-09-25 12:52**MOT test number** 379124572107**Result** ✓ Passed**MOT #3** 2015-09-25 10:52**MOT test number** 465443230250**Result** ✗ Failed

- Fail** Nearside Front coil spring broken (2.4.C.1a)



MOT #2	2014-09-24 11:44
MOT test number	379367364259
Result	✓ Passed

MOT #1	2013-09-18 14:38
MOT test number	266451463205
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
7 June 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	32
<b>MOT expiry date</b>	7 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation


<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-30
Last registration	2023-06-05
Complete history	<a href="#">See info</a>



Registration #1	2010-09-30	19 mi
Registration #2	2013-09-18	13.244 mi
Registration #3	2014-09-24	17.089 mi
Registration #4	2015-09-25	20.312 mi
Registration #5	2015-09-25	20.312 mi
Registration #6	2016-09-19	23.489 mi
Registration #7	2017-09-27	26.270 mi
Registration #8	2017-09-28	26.293 mi
Registration #9	2019-05-29	26.297 mi
Registration #10	2019-05-29	26.297 mi
Registration #11	2019-05-29	26.297 mi
Registration #12	2019-05-29	26.297 mi
Registration #13	2019-05-29	26.297 mi
Registration #14	2019-05-29	26.297 mi
Registration #15	2019-05-29	26.297 mi
Registration #16	2019-05-29	26.297 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	5839116