



TOYOTA




report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 VVTI NV
Colour	Silver
Year of manufacture	2002
Top speed	106 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	158 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 2

Date	2021-10-01
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-30
Pictures	1
Listing price	View report

AA This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com

source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-25
MOT pass rate	78 %
MOT passed	18
Failed MOT tests	5
Total advice items	43
Total items failed	4

MOT #23	2023-09-20 13:58
MOT test number	800799079335
Result	✓ Passed
Next expiry date	2024-09-25
Minor	Headlamp lens slightly defective both sides (4.1.1 (b) (i))

MOT #22	2023-09-18 08:19
MOT test number	692259293049
Result	✗ Failed
Advice	Nearside Rear Nail in tyre
MAJOR	Brake pipe excessively corroded both sides (1.1.11 (c))
Minor	Headlamp lens slightly defective both sides (4.1.1 (b) (i))



MOT #21	2022-09-05 08:14
MOT test number	521424483821
Result	✓ Passed
Minor	Offside Front Steering linkage ball joint ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources nearside bulb out (4.7.1 (b) (i))
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #20	2021-09-20 15:18
MOT test number	704475305366
Result	✓ Passed

MOT #19	2021-08-26 10:16
MOT test number	118583105705
Result	✗ Failed
DANGEROUS	Exhaust shield missing where fitted as original equipment creating a risk of fire insecure (6.1.3 (e))
MAJOR	Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
MAJOR	Brake fluid significantly below minimum mark light on (1.1.10 (d) (ii))
MAJOR	Offside Rear Wheel bearing has excessive play (5.1.3 (a) (i))
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
MAJOR	Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt both sides (5.3.4 (b) (ii))



MOT #18 2020-09-01 14:37

MOT test number 625736022656

Result ✔ Passed

- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))
- Advice** Anti-lock braking system wiring damaged but not excessively (1.6 (d))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #17 2020-09-01 14:37

MOT test number 446225461497

Result ✘ Failed

- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))
- Advice** Anti-lock braking system wiring damaged but not excessively (1.6 (d))
- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #16 2019-09-02 11:54

MOT test number 256752423604

Result ✔ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))

MOT #15 2018-09-26 15:45

MOT test number 600281314540

Result ✔ Passed



MOT #14	2018-09-24 10:34
MOT test number	505152428262
Result	✗ Failed
MAJOR	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
MAJOR	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #13	2017-08-21 12:18
MOT test number	858180204691
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Front Headlamp deteriorated but light output not reduced both sides (1.7.5a)

MOT #12	2016-08-31 08:34
MOT test number	858029128588
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Anti-roll bar ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #11	2015-08-29 11:47
MOT test number	883759015642
Result	✓ Passed

MOT #10	2014-08-29 10:54
MOT test number	147241544211
Result	✓ Passed



MOT #9 2013-08-31 10:58

MOT test number 297283043266

Result ✓ Passed

MOT #8 2013-08-30 10:24

MOT test number 266512043294

Result ✗ Failed

Fail Offside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)

Fail Nearside Stop lamp not working (1.2.1b)

Fail Exhaust has a major leak of exhaust gases (7.1.2)

MOT #7 2012-08-30 16:53

MOT test number 486133942266

Result ✓ Passed

MOT #6 2011-08-30 13:00

MOT test number 885162241232

Result ✓ Passed

MOT #5 2010-09-03 09:58

MOT test number 260546240276

Result ✓ Passed



MOT #4 2009-03-09 14:36

MOT test number 800278869086

Result ✔ Passed

- Notice** Rear wiper blade is torn
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front front brake juddering slightly (3.7.A.2b)
- Notice** Front wiper blade is torn sightly
- Notice** Rear brake discs slightly corroded
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #3 2008-07-31 11:26

MOT test number 793423318202

Result ✔ Passed

- Advice** Brake disc slightly pitted (3.5.1h)
- Notice** Rear bush on both front wishbones perishing

MOT #2 2007-07-30 16:36

MOT test number 904541417252

Result ✔ Passed

MOT #1 2006-07-27 10:34

MOT test number 204348906231

Result ✔ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
25 September 2024

Tax status	Valid until 1 October
Days left	155
MOT expiry date	25 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	SG52HKW
Plate since	2019-09-29
Current registration	SG52HKW
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2002-10-31
Last registration	2023-09-20
Complete history	See info



Registration #1	2002-10-31	19 mi
Registration #2	2006-07-27	20.153 mi
Registration #3	2007-07-30	30.880 mi
Registration #4	2008-07-31	41.707 mi
Registration #5	2009-03-09	49.596 mi
Registration #6	2010-09-03	54.936 mi
Registration #7	2011-08-30	58.573 mi
Registration #8	2012-08-30	60.957 mi
Registration #9	2013-08-30	65.219 mi
Registration #10	2013-08-31	65.215 mi
Registration #11	2014-08-29	68.667 mi
Registration #12	2015-08-29	71.793 mi
Registration #13	2016-08-31	75.350 mi
Registration #14	2016-08-31	75.350 mi
Registration #15	2016-08-31	75.350 mi
Registration #16	2016-08-31	75.350 mi
Registration #17	2016-08-31	75.350 mi
Registration #18	2016-08-31	75.350 mi
Registration #19	2016-08-31	75.350 mi
Registration #20	2016-08-31	75.350 mi
Registration #21	2016-08-31	75.350 mi
Registration #22	2016-08-31	75.350 mi
Registration #23	2016-08-31	75.350 mi
Registration #24	2016-08-31	75.350 mi
Registration #25	2016-08-31	75.350 mi
Registration #26	2016-08-31	75.350 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1700 mm
Length	3865 mm
Wheel base	2280 mm
Kerb weight	1235 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1ZZ1022556