





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOUAREG V6 TDI
Colour	Black
Year of manufacture	2008
Top speed	125 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	500 Nm at 1.750 rpm
Engine capacity	2.967 сс
Cylinders	6
Fuel type	Diesel
Consumption city	19.9 mpg
Consumption extra urban	33.6 mpg
Consumption combined	26.9 mpg
CO2 emission	278 g/km
CO2 label	M



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-07-08

Pictures 50

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-09-21
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	28
Total items failed	3

MOT #16	2023-09-22 11:00
MOT test number	206671697350
Result	✓ Passed
Next expiry date	2024-09-21
Advice Rear Upper Suspension arm pin or bush worn but not resulting in excession nearside (5.3.4 (a) (i))	ve movement offside &
Advice Parking brake lever has little reserve travel & efficiency just met limit	
Advice Brake hose slightly deteriorated both front & both rear (1.1.12 (b) (ii))	
Advice Offside Rear Outer sidelight not working	

MOT #15		2023-09-21 11:51
MOT test	number	277970673527
Result		🗙 Failed
MAJOR	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice nearside (!	Rear Upper Suspension arm pin or bush worn but not resulting in excessive 5.3.4 (a) (i))	movement offside &
Advice	Parking brake lever has little reserve travel & efficiency just met limit	
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Brake hose slightly deteriorated both front & both rear (1.1.12 (b) (ii))	
Advice	Offside Rear Outer sidelight not working	

CarCheck.co.uk page 3/13



Result

E5NAC report date: 2024-03-28

✓ Passed

MOT #14 2022-07-12 14:22

MOT test number 688928417265

Result ✓ Passed

Advice Offside rear outer sidelight not working

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear Upper Suspension arm pin or bush worn but not resulting in excessive movement inner bushes, offside & nearside (5.3.4 (a) (i))

Advice Parking brake efficiency only just met requirements & lever travel high

Advice Brake hose slightly deteriorated front & rear (1.1.12 (b) (ii))

MOT #13 2021-07-14 09:43

MOT test number 198556245391

MOT #12 2020-07-14 16:07

MOT test number 753742739153

MOT #11 2019-08-16 12:02

MOT test number 614061004899

Result
✓ Passed

MOT #10 2018-06-16 07:48

MOT test number 682316451022

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



MOT #9 2018-06-15 10:43

MOT test number 966481156552

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front tyre is worn bald on inner tread and has cuts on side wall

MOT #8 2016-12-06 13:04

MOT test number 372987754178

Result ✓ Passed

MOT #7 2016-12-06 13:04

MOT test number 699432446308

Result X Failed

Pass with rectification Nearside Headlamp not working on dipped beam (1.7.5a)

Pass with rectification Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #6 2015-10-12 08:11

MOT test number 430489541932

Result J Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit worn very close and worn bald on inner tread

(4.1.E.1)

CarCheck.co.uk page 5/13



MOT #5 2015-10-08 14:52

MOT test number 491753633179

Result X Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Nearside Registration plate lamp insecure (1.1.C.1c)

Advice Offside Front Tyre worn close to the legal limit worn very close and worn bald on inner tread (4.1.E.1)

MOT #4 2014-09-30 15:38

MOT test number 775553774235

Result ✓ Passed

MOT #3 2013-09-03 10:59

MOT test number 337906443436

Result ✓ Passed

MOT #2 2012-03-26 10:34

MOT test number 236126882071

Result

Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Wear to o/s/f tyre possible tracking

MOT #1 2011-03-25 14:36

MOT test number 297864281018

Result
✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	21 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



E5NAC

report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many volkswagen have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK NE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-02-26
Last registration	2023-09-22
Complete history	See info



Registration #1	2008-02-26	24 mi
Registration #2	2011-03-25	32.296 mi
Registration #3	2012-03-26	40.407 mi
Registration #4	2013-09-03	52.554 mi
Registration #5	2014-09-30	57.920 mi
Registration #6	2015-10-08	64.764 mi
Registration #7	2015-10-12	64.764 mi
Registration #8	2016-12-06	76.364 mi
Registration #9	2016-12-06	76.364 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		71.777 es

More info >

page 12/13 CarCheck.co.uk



Car features

	ım report.
S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1928 mm
Height	1726 mm
Length	4754 mm
Wheel base	2855 mm
Max. allowed weight	2945 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

CarCheck.co.uk page 13/13

Number of axles	2

BKS 081949

Engine number