



report date: 2024-09-18

General information

Make	MINI
Model	CLUBVAN COOPER D
Colour	Black
Year of manufacture	2013
Top speed	119 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.250 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E





Internet history

Entry 1

Date	2023-08-22
Pictures	38
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2025-10-09
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	8
Total items failed	0

MOT #11 2024-09-20 15:48

MOT test number 974896497964

Result ✓ Passed

Next expiry date 2025-10-09

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10 2023-10-10 13:01

MOT test number 117412521226

Result ✓ Passed

MOT #9 2023-05-19 08:09

MOT test number 646170280042

Result ✓ Passed

MOT #8 2022-07-05 11:35

MOT test number 798282457105

Result ✓ Passed

MOT #7 2021-07-06 09:53

MOT test number 117588253903

Result ✓ Passed

Advice Rear Inner Brake pad(s) wearing thin Both side (1.1.13 (a) (ii))



MOT #6 2020-07-14 12:11

MOT test number 732709561501

Result ✔ Passed

Advice Rear Inner Brake pad(s) wearing thin Both side (1.1.13 (a) (ii))

MOT #5 2020-07-10 08:50

MOT test number 177383866214

Result ✘ Failed

MAJOR Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Rear Inner Brake pad(s) wearing thin Both side (1.1.13 (a) (ii))

MOT #4 2019-07-11 14:34

MOT test number 917755276405

Result ✔ Passed

MOT #3 2019-07-11 09:49

MOT test number 612838826400

Result ✘ Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge and Perishing (5.2.3 (e))

Advice Tyre slightly damaged/cracking or perishing Both rear (5.2.3 (d) (ii))

DANGEROUS Offside Front Tyre has a lump, caused by separation or partial failure of its structure Outside wall (5.2.3 (d) (ii))

MOT #2 2018-07-12 08:31

MOT test number 566577799108

Result ✔ Passed

MOT #1 2017-07-14 11:24

MOT test number 497748103306

Result ✔ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 October 2025

✓
MOT

Expires:
9 October 2025

Tax status Valid until 1 October

Days left 361

MOT expiry date 9 October 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	OY63USU
Plate since	2019-09-18
Current registration	OY63USU
Plate since	2019-09-18

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-10-28
Last registration	2024-09-20
Complete history	See info



Registration #1	2013-10-28	14 mi
Registration #2	2017-07-14	31.603 mi
Registration #3	2018-07-12	38.085 mi
Registration #4	2019-07-11	42.807 mi
Registration #5	2019-07-11	42.807 mi
Registration #6	2020-07-10	45.770 mi
Registration #7	2020-07-14	45.825 mi
Registration #8	2020-07-14	45.825 mi
Registration #9	2020-07-14	45.825 mi
Registration #10	2020-07-14	45.825 mi
Registration #11	2020-07-14	45.825 mi
Registration #12	2020-07-14	45.825 mi
Registration #13	2020-07-14	45.825 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1913 mm
Height	1426 mm
Length	3961 mm
Kerb weight	1215 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	94828719