

\$ SUZUKI



General information

Make	SUZUKI
Model	SPLASH SZ3
Colour	Purple
Year of manufacture	2012
Top speed	99 mph
0 - 60 mph	14.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 4.800 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	67.3 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	В







Internet history		
Entry 1		
Date	2021-06-14	
Pictures	0	
Listing price	View report	

source: autotrader.co.uk



MOT history

MOT expiry date	2024-06-28
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	29
Total items failed	0

MOT #10		2023-06-20 12:17
MOT test r	number	242255090634
Result		🗸 Passed
Next expir	ry date	2024-06-28
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Rear Inner Brake hose has slight corrosion to ferrule ON BOTH SIDES (1.1.12 (f) (i))
Advice	Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		

MOT #9		2022-06-16 13:43
MOT test	number	610763741522
Result		✓ Passed
Advice	Offside Rear Inner Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.1	1 (c))
Advice	Nearside Rear Inner Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))





MOT #8		2022-06-10 09:47
MOT test	number	985136993357
Result		🗙 Failed
Advice	Nearside Rear Inner Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 ($lpha$	2))
Advice	Offside Rear Inner Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
MAJOR (5.2.3 (d) (Nearside Rear Tyre has a cut in excess of the requirements deep enough to read (i))	ch the ply or cords
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11	(c))

MOT #7	2021-06-29 13:49
MOT test number	719764477662
Result	✓ Passed

МОТ #6	2020-12-18 13:41
MOT test number	620901770718
Result	✓ Passed
Minor Nearside Front Windscreen wiper blade defective torn on edges (3.4 (b) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Front Upper Shock absorbers has a slightly worn bush top mount (5.3	3.2 (c))
Minor Offside Front Windscreen wiper blade defective torn on edges (3.4 (b) (i))	





MOT #5		2019-12-12 10:41
MOT test	number	138778222493
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Outer Tyre slightly damaged sidewall has slight damage (5.2.3 ((d) (ii))
Advice	Offside Front Upper Shock absorbers has a slightly worn bush mount has slight	play (5.3.2 (c))

МОТ #4	2018-12-13 16:36
MOT test number	671707998329
Result	✓ Passed

MOT #3		2017-12-14 09:36
MOT test	number	743083911918
Result		✓ Passed
Advice	Parking brake lever has little reserve travel (3.1.6b)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Nail in tyre	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #2	2016-12-15 17:27
MOT test number	374454154647
Result	✓ Passed
MOT #1	2015 12 04 17.24

MOI #1	2015-12-04 17:24
MOT test number	471067430718
Result	✓ Passed





Tax & MOT check

Tax due: 1 July 2024	ed	Expires: 28 June 2024	√ мот
Tax status			Valid until 1 July
Days left			64
MOT expiry date			28 June 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra SUZUKI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And the second sec	

	More info >
Plate changes	
See in this check if this SUZUKI had different number pla	tes.
Number of plates	9
Current registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2012-12-21
Last registration	2023-06-20
Complete history	See info



Registration #1	2012-12-21	17 mi
Registration #2	2015-12-04	12.752 mi
Registration #3	2016-12-15	15.616 mi
Registration #4	2017-12-14	19.979 mi
Registration #5	2018-12-13	23.793 mi
Registration #6	2019-12-12	26.418 mi
Registration #7		11.777 esi
Registration #7 Registration #8		20.000 est
		01,000 est 01,000 est 01,000 est
Registration #8		01,000 est 01,000 est 01,000 est 01,000 est
Registration #8 Registration #9		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1680 mm
Height	1590 mm
Length	3775 mm
Wheel base	2360 mm
Kerb weight	1075 kg
Max. allowed weight	1485 kg
Additional information	
Additional information Fuel tank capacity	45 l
	45 l Multi-Point Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Multi-Point Injection
Fuel tank capacity Fuel delivery Number of doors	Multi-Point Injection 5