





report date: 2024-03-29

General information

Make	MERCEDES
Model	CLS CLS320 CDI
Colour	Silver
Year of manufacture	2007
Top speed	148 mph
0 - 60 mph	7.0 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 сс
Cylinders	6
Fuel type	Diesel
Consumption city	27.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	27.7 mpg
CO2 emission	200 g/km
CO2 label	J



CarCheck.co.uk page 1/16



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-27

Pictures 30

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-29

MOT history

MOT expiry date	2024-04-19
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	47
Total items failed	14

MOT #22	2023-04-20 09:03
MOT test number	953925959734
Result	✓ Passed
Next expiry date	2024-04-19
Advice Nearside Front Tyre worn on inner edge	
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice Offside Front Tyre worn on inner edge	

MOT #21		2023-04-11 08:32
MOT test	number	615237067944
Result		× Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))	
Fail N	earside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))	
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

CarCheck.co.uk page 3/16



Result

OV07EXU

report date: 2024-03-29

Passed

MOT #20 2022-04-02 13:26

MOT test number 236140742843

Result ✓ Passed

Advice Front Tyre worn close to legal limit/worn on edge both side inner shoulder worn (5.2.3 (e))

MOT #19 2021-03-29 15:34

MOT test number 186007290452

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #18 2021-03-27 10:33

MOT test number 432849275628

Result X Failed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources Intermittent fault (4.7.1 (b) (i))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #17 2020-01-29 09:42

MOT test number 501983172709

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge wearing inner edge/nail (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

CarCheck.co.uk page 4/16



report date: 2024-03-29

MOT #16 2020-01-28 14:31

MOT test number 397697970834

Result X Failed

Fail Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt rearmost (5.3.4 (b) (ii))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure inner wall (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge wearing inner edge/nail (5.2.3 (e))

Advice Offside Front tyre wearing inner edge

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #15 2019-01-24 11:27

MOT test number 191333867809

Result \sqrt{Passed}

MOT #14 2018-02-05 17:53

MOT test number 792436261325

Result \(\sqrt{Passed} \)

MOT #13 2018-02-05 17:53

MOT test number 366207027139

Result X Failed

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 5/16



report date: 2024-03-29

MOT #12 2017-06-17 10:02 **MOT** test number 371966363624 Result ✓ Passed **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Rear coil spring corroded (2.4.C.1b) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Offside Front wheel bearing has slight play (2.5.A.3c) **Advice** Nearside Rear Track rod end ball joint has slight play (2.2.B.1f)

MOT #11 2016-06-17 14:28
MOT test number 796455417484
Result ✓ Passed

MOT #10 2016-06-16 11:14

MOT test number 127617003931

Result X Failed

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

 MOT #9
 2015-06-19 10:57

 MOT test number
 676950675131

 Result
 ✓ Passed

CarCheck.co.uk page 6/16



report date: 2024-03-29

MOT test number 695532364142

Result ✓ Passed

Notice Oil leak

Notice Wipers are poor

Notice Gearbox under-shield is broken

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #7

MOT test number

S15571573151

Result

Notice Checked and adjusted tyre pressures. Have reset tyre pressure monitoring system

MOT test number
759881873172

Result

Pass with rectification
Offside Headlamp aim too low (1.8)

Pass with rectification
Nearside Headlamp aim too low (1.8)

Notice
Checked and adjusted tyre pressures. Have reset tyre pressure monitoring system

MOT #5

MOT test number

426043672107

Result

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

 MOT #4
 2011-06-18 09:32

 MOT test number
 205819061158

 Result
 ✓ Passed

CarCheck.co.uk page 7/16



report date: 2024-03-29

MOT test number

837018761124

Result

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #2		2010-04-16 16:44
MOT test	number	363286100197
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Front Road wheel slightly damaged (4.2.A.1a)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Advice	Offside Front Road wheel slightly damaged (4.2.A.1a)	

CarCheck.co.uk page 8/16



report date: 2024-03-29

2010-04-15 15:59 **MOT #1** 911875700189 **MOT** test number Result × Failed **Advice** Offside Front Road wheel slightly damaged (4.2.A.1a) Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Offside Front Brake pad(s) wearing thin (3.5.1g) Fail Nearside Front Road wheel badly damaged (4.2.A.1a) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 9/16



report date: 2024-03-29

Tax & MOT check





Tax status	Valid until 1 November
Days left	185
MOT expiry date	19 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 10/16




report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra MERCEDES salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



OV07EXU report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 12/16



OV07EXU report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many own MERCEDES have? Check it in the premium report and see all owner registrations. Downloadere.	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NK NA
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 13/16



report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2007-04-12
Last registration	2023-04-20
Complete history	See info



Registration #2 2010-04-15 31.134 m Registration #3 2010-04-16 31.141 m Registration #4 2011-06-17 38.889 m Registration #5 2011-06-18 38.911 m Registration #6 2012-06-21 48.376 m Registration #7 2013-06-20 55.466 m Registration #8 2014-06-11 64.279 m Registration #9 2015-06-19 69.966 m Registration #10 2016-06-16 77.890 m Registration #11 2016-06-17 77.891 m			
Registration #3	Registration #1	2007-04-12	25 mi
Registration #4 2011-06-17 38.889 m Registration #5 2011-06-18 38.911 m Registration #6 2012-06-21 48.376 m Registration #7 2013-06-20 55.466 m Registration #8 2014-06-11 64.279 m Registration #9 2015-06-19 69.966 m Registration #10 2016-06-16 77.890 m Registration #11 2016-06-17 77.891 m Registration #12 2017-06-17 84.949 m Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #19 Registration #20 Registration #21 Registration #22	Registration #2	2010-04-15	31.134 mi
Registration #5 Registration #6 2012-06-21 48.376 m Registration #7 2013-06-20 55.466 m Registration #8 2014-06-11 64.279 m Registration #9 2015-06-19 69.966 m Registration #10 2016-06-16 77.890 m Registration #11 2016-06-17 77.891 m Registration #12 2017-06-17 84.949 m Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #19 Registration #20 Registration #20 Registration #20 Registration #20 Registration #20	Registration #3	2010-04-16	31.141 mi
Registration #6 2012-06-21 48.376 m Registration #7 2013-06-20 55.466 m Registration #8 2014-06-11 64.279 m Registration #9 2015-06-19 69.966 m Registration #10 2016-06-16 77.890 m Registration #11 2016-06-17 77.891 m Registration #12 2017-06-17 84.949 m Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #19 Registration #20 Registration #21 Registration #22	Registration #4	2011-06-17	38.889 mi
Registration #7 Registration #8 2014-06-11 64.279 m Registration #9 2015-06-19 Registration #10 2016-06-16 77.890 m Registration #11 2016-06-17 Registration #12 2017-06-17 Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #20 Registration #21 Registration #22	Registration #5	2011-06-18	38.911 mi
Registration #8 2014-06-11 64.279 m Registration #9 2015-06-19 69.966 m Registration #10 2016-06-16 77.890 m Registration #11 2016-06-17 77.891 m Registration #12 2017-06-17 84.949 m Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21	Registration #6	2012-06-21	48.376 mi
Registration #9 2015-06-19 69.966 m Registration #10 2016-06-16 77.890 m Registration #11 2016-06-17 77.891 m Registration #12 2017-06-17 84.949 m Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #7	2013-06-20	55.466 mi
Registration #10 2016-06-16 77.890 m Registration #11 2016-06-17 77.891 m Registration #12 2017-06-17 84.949 m Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #8	2014-06-11	64.279 mi
Registration #11 2016-06-17 77.891 m Registration #12 2017-06-17 84.949 m Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21	Registration #9	2015-06-19	69.966 mi
Registration #12 2017-06-17 84.949 m Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #21	Registration #10	2016-06-16	77.890 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #11	2016-06-17	77.891 mi
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #12	2017-06-17	84.949 mi
Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #13		11.777 es
Registration #15 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #14		71.777 es
Registration #17 Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #15		11.777 es
Registration #18 Registration #19 Registration #20 Registration #21 Registration #22	Registration #16		77,777 46
Registration #19 Registration #20 Registration #21 Registration #22	Registration #17		11.777 es
Registration #20 Registration #21 Registration #22	Registration #18		71.777 es
Registration #21 Registration #22	Registration #19		71.777 es
Registration #22	Registration #20		D.777 es
-	Registration #21		11.777 es
Registration #23	Registration #22		71.777 es

More info >

CarCheck.co.uk page 15/16



OV07EXU report date: 2024-03-29

Safety ratings

NCAP rating	****
-------------	------

Video <u>see crash video</u>



Dimensions & weight

Width	2059 mm
Height	1403 mm
Length	4913 mm
Wheel base	2854 mm
Kerb weight	1815 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	64292040446156

CarCheck.co.uk page 16/16