



RENAULT

KM59ZWS

report date: 2024-03-29

General information

Make	RENAULT
Model	GRAND SCENIC TOMTOM EDITION DCI
Colour	Black
Year of manufacture	2009
Top speed	111 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-07-30
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-05
MOT pass rate	65 %
MOT passed	13
Failed MOT tests	7
Total advice items	41
Total items failed	8

MOT #20 2024-03-01 10:39

MOT test number 579831996522

Result ✓ Passed

Next expiry date 2025-03-05

Advice Headlamp has a product on the light source but not seriously reducing light output both (4.1.4 (b))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Advice Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))

MOT #19 2024-03-01 10:39

MOT test number 558087754247

Result ✗ Failed

Advice Tyre worn close to legal limit/worn on edge both rear (5.2.3 (e))

Pass with rectification Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Advice Headlamp has a product on the light source but not seriously reducing light output both (4.1.4 (b))

MOT #18 2023-02-27 14:59

MOT test number 246093115470

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17**

2023-02-24 14:53

MOT test number

206243596289

Result**✗ Failed****Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #16**

2022-02-23 09:35

MOT test number

481005695530

Result**✓ Passed****Advice** Nearside Front Play in steering rack inner joint(s)**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #15**

2021-03-03 13:58

MOT test number

545924759439

Result**✓ Passed**



MOT #14	2021-03-03 09:19
MOT test number	789828634810
Result	✗ Failed
<div>Fail</div> Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
MOT #13	2020-02-17 14:33
MOT test number	239961410889
Result	✓ Passed
MOT #12	2019-02-18 10:29
MOT test number	179233709555
Result	✓ Passed
MOT #11	2018-03-06 17:07
MOT test number	101749136677
Result	✓ Passed
MOT #10	2017-06-29 08:33
MOT test number	274957774442
Result	✓ Passed

**MOT #9**

2016-11-16 11:28

MOT test number

818244702785

Result

✓ Passed

Advice Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front cut to tyre sidewall 205/60/16

Advice Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #8

2016-11-16 10:45

MOT test number

756429736658

Result

✗ Failed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Outer Front constant velocity joint gaiter damaged, but preventing the ingress of dirt (2.5.C.1a)

Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Advice Offside Front cut to tyre sidewall 205/60/16

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7

2015-11-11 12:29

MOT test number

358425365519

Result

✓ Passed

**MOT #6** 2015-11-11 11:20**MOT test number** 191768551225**Result** ✗ Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
2056016h (4.1.D.1a)

MOT #5 2014-12-04 14:55**MOT test number** 665818834373**Result** ✓ Passed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Outer Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

MOT #4 2014-11-28 12:32**MOT test number** 747642334309**Result** ✗ Failed

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Nearside Outer Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Nearside Outer Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

Notice Oil leak

MOT #3 2013-12-06 12:57**MOT test number** 736150943321**Result** ✓ Passed

Notice Child seat fitted not allowing full inspection of adult belt

Notice Under-trays fitted obscuring some underside components



MOT #2	2013-12-06 12:32
MOT test number	907050743326
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Under-trays fitted obscuring some underside components
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2012-12-11 11:03
MOT test number	337376442340
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
5 March 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	5 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-12-04
Last registration	2024-03-01
Complete history	See info



Registration #1	2009-12-04	28 mi
Registration #2	2012-12-11	40.177 mi
Registration #3	2013-12-06	50.868 mi
Registration #4	2013-12-06	50.868 mi
Registration #5	2014-11-28	63.364 mi
Registration #6	2014-12-04	63.545 mi
Registration #7	2015-11-11	74.162 mi
Registration #8	2015-11-11	74.162 mi
Registration #9	2016-11-16	86.557 mi
Registration #10	2016-11-16	86.557 mi
Registration #11	2017-06-29	92.276 mi
Registration #12	2017-06-29	92.276 mi
Registration #13	2017-06-29	92.276 mi
Registration #14	2017-06-29	92.276 mi
Registration #15	2017-06-29	92.276 mi
Registration #16	2017-06-29	92.276 mi
Registration #17	2017-06-29	92.276 mi
Registration #18	2017-06-29	92.276 mi
Registration #19	2017-06-29	92.276 mi
Registration #20	2017-06-29	92.276 mi
Registration #21	2017-06-29	92.276 mi
Registration #22	2017-06-29	92.276 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1935 kg

Additional information

Fuel tank capacity	49 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D124223