



report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO SOUND
Colour	Grey
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-09-25
Pictures	11
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-02-25
MOT pass rate	63 %
MOT passed	12
Failed MOT tests	7
Total advice items	45
Total items failed	10

MOT #19 2024-02-21 18:07

MOT test number 983820002985

Result ✓ Passed

Next expiry date 2025-02-25

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Exhaust system corroded
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both rear bushes (5.3.4 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Advice** Front subframe covered in thick black substance used c/a/t tool all ok time of test
- Advice** Rear Lower Gearbox mounting defective
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #18 2023-02-15 12:43

MOT test number 260384854958

Result ✓ Passed

- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both sides wishbone rear (5.3.4 (a) (i))

MOT #17 2022-02-23 18:47

MOT test number 661333500922

Result ✓ Passed

**MOT #16**

2022-02-21 18:56

**MOT test number**

375924966797

**Result**

✗ Failed

**Fail** Nearside Front Anti-roll bar linkage missing (5.3.3 (a) (ii))**Fail** Offside Front Anti-roll bar linkage missing (5.3.3 (a) (ii))**MOT #15**

2021-02-26 18:26

**MOT test number**

549285834662

**Result**

✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14**

2020-02-26 16:11

**MOT test number**

113393394343

**Result**

✓ Passed

**Advice** Shock absorbers light misting of oil or has limited damping effect both front shockers (5.3.2 (b))**Advice** Nearside Front tyre worn bald on inner edge and cracks on outer edge**Advice** Front brake pads worn low and discs lipped**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear exhaust box surround cover corroded**Advice** Both front top suspension mountings slightly rough when turning [no excessive movement]

**MOT #13**

2020-02-22 12:33

**MOT test number**

402563701518

**Result****✗ Failed**

- Advice** Nearside Front tyre worn bald on inner edge and cracks on outer edge
- Advice** Front brake pads worn low and discs lipped
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Shock absorbers light misting of oil or has limited damping effect both front shockers (5.3.2 (b))
- Advice** Rear exhaust box surround cover corroded
- Advice** Both front top suspension mountings slightly rough when turning [no excessive movement]
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Nearside Front Windscreen damaged and affecting the driver's view of the road cracked (3.2 (a) (ii))

**MOT #12**

2019-02-02 11:31

**MOT test number**

621182803254

**Result****✓ Passed**

- Advice** Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Both rear coil springs corroded
- Advice** Rear exhaust box / surround corroded
- Advice** Front brake discs lipped

**MOT #11** 2019-02-02 11:31**MOT test number** 398307967873**Result** ✗ Failed**Advice** Rear exhaust box / surround corroded**Advice** Front brake discs lipped**Advice** Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Both rear coil springs corroded**MOT #10** 2018-02-09 10:15**MOT test number** 420513962235**Result** ✓ Passed**MOT #9** 2017-02-09 15:31**MOT test number** 734277701781**Result** ✓ Passed**Advice** Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)**MOT #8** 2016-02-24 12:57**MOT test number** 334631210379**Result** ✓ Passed**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #7** 2016-02-24 12:20**MOT test number** 186504574699**Result** ✗ Failed**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** Offside Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2015-02-16 12:57**MOT test number** 617737445002**Result** ✓ Passed**Notice** Items removed from driver's view prior to test**MOT #5** 2015-02-16 12:57**MOT test number** 966877245099**Result** ✗ Failed**Notice** Items removed from driver's view prior to test**Pass with rectification** Nearside Headlamp aim too high (1.8)**MOT #4** 2014-02-01 12:13**MOT test number** 649362934026**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test



MOT #3	2014-02-01 12:13
MOT test number	547652634040
Result	✗ Failed
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Items removed from driver's view prior to test
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2013-02-16 09:53
MOT test number	519917043063
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2013-02-16 09:53
MOT test number	757857243079
Result	✗ Failed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Nearside Front Headlamp not working on dipped beam (1.7.5a)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
25 February 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	25 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-02-18
Last registration	2024-02-21
Complete history	<a href="#">See info</a>



Registration #1	2010-02-18	18 mi
Registration #2	2013-02-16	58.340 mi
Registration #3	2014-02-01	68.716 mi
Registration #4	2015-02-16	82.304 mi
Registration #5	2016-02-24	90.756 mi
Registration #6	2016-02-24	90.759 mi
Registration #7	2017-02-09	95.217 mi
Registration #8	2018-02-09	98.358 mi
Registration #9	2019-02-02	100.804 mi
Registration #10	2020-02-02	100.804 mi
Registration #11	2020-02-02	100.804 mi
Registration #12	2020-02-02	100.804 mi
Registration #13	2020-02-02	100.804 mi
Registration #14	2020-02-02	100.804 mi
Registration #15	2020-02-02	100.804 mi
Registration #16	2020-02-02	100.804 mi
Registration #17	2020-02-02	100.804 mi
Registration #18	2020-02-02	100.804 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	9632561
---------------	---------