



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT3
Colour	Grey
Year of manufacture	2006
Top speed	112 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.9 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	173 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-12-18
Pictures	21
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-13
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	42
Total items failed	15

MOT #22	2023-11-22 10:39
MOT test number	874664597215
Result	✓ Passed
Next expiry date	2024-12-13

MOT #21	2023-11-22 10:39
MOT test number	409185738896
Result	✗ Failed
Pass with rectification Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))	

MOT #20	2022-11-22 08:45
MOT test number	153459636367
Result	✓ Passed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #19	2021-12-14 16:13
MOT test number	504913854395
Result	✓ Passed

**MOT #18** 2021-03-31 16:40**MOT test number** 765958205027**Result** ✓ Passed**MOT #17** 2021-03-30 15:58**MOT test number** 736605165241**Result** ✗ Failed**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Rear Fuel pipe leaking excessively or a risk of fire Filler Pipe Corroded Holed (6.1.3 (b) (ii))**MOT #16** 2020-12-15 11:48**MOT test number** 402424066750**Result** ✗ Failed**Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #15** 2019-05-02 10:56**MOT test number** 579283374174**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #14**

2019-05-02 10:56

MOT test number

706206668858

Result**✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on outer edge (5.2.3 (e))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13**

2018-03-27 12:04

MOT test number

620037823702

Result**✓ Passed****Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #12**

2017-04-25 10:52

MOT test number

130519378421

Result**✓ Passed****Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Rear reflector slightly damaged but function not impaired (1.5.1c)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)

**MOT #11** 2016-02-11 15:00**MOT test number** 883623802365**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit perished and worn on inner edge (4.1.E.1)**Advice** Offside front tyre worn on outer edge**Advice** Nearside front tyre worn on outer edge**MOT #10** 2015-02-10 16:29**MOT test number** 815731445011**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2015-02-10 16:10**MOT test number** 109651645469**Result** ✓ Passed

**MOT #8**

2015-02-09 13:48

MOT test number

156830645439

Result**✗ Failed**

- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)
- Advice** Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)
- Fail** Nearside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)

MOT #7

2014-02-02 15:17

MOT test number

276703334094

Result**✓ Passed**

- Notice** Offside rear tyre was manufactured in 2006, is worn close to legal limit and has cracks in tread and sidewalls
- Notice** Rear brake pads about 70% worn
- Notice** Nearside rear tyre was manufactured in 2006, is worn close to legal limit and has cracks in tread and sidewalls
- Notice** Both rear brake discs worn/corroded
- Notice** Service indicator on

**MOT #6** 2014-02-01 14:50**MOT test number** 189922134412**Result** ✗ Failed**Notice** Rear brake pads about 70% worn**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Nearside rear tyre was manufactured in 2006, is worn close to legal limit and has cracks in tread and sidewalls**Notice** Both rear brake discs worn/corroded**Notice** Service indicator on**Notice** Offside rear tyre was manufactured in 2006, is worn close to legal limit and has cracks in tread and sidewalls**MOT #5** 2013-01-17 13:30**MOT test number** 345847813050**Result** ✓ Passed**MOT #4** 2013-01-16 10:47**MOT test number** 659086713085**Result** ✗ Failed**Fail** Nearside Front Lower Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #3** 2011-12-09 09:44**MOT test number** 497713541351**Result** ✓ Passed**MOT #2** 2010-12-22 10:42**MOT test number** 870696150389**Result** ✓ Passed



MOT #1	2009-12-09 09:58
MOT test number	620743749329
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
13 December 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	13 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	YG56DKU
Plate since	2019-03-29
Current registration	YG56DKU
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-09-08
Last registration	2023-11-22
Complete history	See info



Registration #1	2006-09-08	12 mi
Registration #2	2009-12-09	35.727 mi
Registration #3	2010-12-22	71.649 mi
Registration #4	2011-12-09	64.578 mi
Registration #5	2013-01-16	77.588 mi
Registration #6	2013-01-17	77.588 mi
Registration #7	2014-02-01	90.515 mi
Registration #8	2014-02-02	90.545 mi
Registration #9	2015-02-09	102.358 mi
Registration #10	2015-02-10	102.358 mi
Registration #11	2015-02-10	102.360 mi
Registration #12	2016-02-11	106.926 mi
Registration #13	2016-02-11	106.926 mi
Registration #14	2016-02-11	106.926 mi
Registration #15	2016-02-11	106.926 mi
Registration #16	2016-02-11	106.926 mi
Registration #17	2016-02-11	106.926 mi
Registration #18	2016-02-11	106.926 mi
Registration #19	2016-02-11	106.926 mi
Registration #20	2016-02-11	106.926 mi
Registration #21	2016-02-11	106.926 mi
Registration #22	2016-02-11	106.926 mi
Registration #23	2016-02-11	106.926 mi
Registration #24	2016-02-11	106.926 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1815 mm
Height	1685 mm
Length	4395 mm
Wheel base	2560 mm
Kerb weight	1585 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2AD0082158