





report date: 2024-03-29

#### General information

Make	MINI
Model	MINI (R60) COOPER SD
Colour	White
Year of manufacture	2011
Top speed	123 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	65.7 mpg
Consumption combined	61.4 mpg
CO2 emission	122 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history

#### Entry 1


Date 2021-02-02

Pictures 3

Listing price <u>View report</u>







source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

## MOT history

MOT expiry date	2025-02-10
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	12
Total items failed	4

MOT #11	2024-02-06 11:56
MOT test number	472781962989
Result	✓ Passed
Next expiry date	2025-02-10
Advice Nearside Rear Tyre worn close to legal limit/worn on edge Wearing smooth on inner edge (5.2.3 (e))	
Minor Offside Front Lower Suspension arm ball joint dust cover severely deterior	rated (5.3.4 (b) (i))

MOT #10	2023-02-10 16:4	42
MOT test numb	95988730404	<del></del> 45
Result	✓ Passe	ed
	le Front Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i)) ne x under covers fitted / slight stepping on n/s/r tyre / slight corrosion on rear discs	

MOT #9	2022-02-05 16:44
MOT test number	909292547210
Result	<b>✓</b> Passed
MOT #8	2021-02-11 13:39
MOT test number	674756281932
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #7

MOT test number

S88215282605

Result

Advice Offside front tyre on 3.5mm tread depth.

Advice Rear brake disc's corroded on edges.

**MOT** #6 2020-07-18 08:42 **MOT** test number 718292201578 Result **X** Failed **Advice** Offside front tyre on 3.5mm tread depth. Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Rear brake disc's corroded on edges. **Advice** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) Fail (ii)) Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #5		2019-05-01 12:47
MOT test	number	540632719733
Result		<b>✓</b> Passed
MOT #4		2018-01-19 14:52
MOT test	number	629719829731
Result		✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	

MOT #3	2017-03-13 10:03
MOT test number	795220826210
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #2 2015-12-05 13:55

**MOT test number** 364225602145

**Result** ✓ Passed

MOT #1 2014-12-06 12:21

**MOT test number** 667540044398

Result Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Notice** Engine covers fitted obscuring some components in the engine bay

**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

CarCheck.co.uk page 5/12



YE61WHC
report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	10 February 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

icton
istory

For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report is		e?
THE STATE OF THE S		
***************************************		
***************************************		
********		
***************************************		
	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2011-12-13
Last registration	2024-02-06
Complete history	See info



Registration #1	2011-12-13	26 mi
Registration #2	2014-12-06	24.179 mi
Registration #3	2015-12-05	35.444 mi
Registration #4	2017-03-13	41.812 mi
Registration #5	2018-01-19	43.669 mi
Registration #6	2019-05-01	45.858 mi
Registration #7	2020-07-18	47.197 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 mi
Registration #12		11.777 46
Registration #13		70.777 esc

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

# Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



# Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1320 kg
Max. allowed weight	1790 kg

# Additional information

Fuel tank capacity	47	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 73237973