





report date: 2024-03-28

General information

Make	HYUNDAI
Model	TUCSON GDI SE NAV BLUE DRIVE
Colour	White
Year of manufacture	2018
Top speed	113 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	161 Nm at 4.850 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.8 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/11



VN18XLE

report date: 2024-03-28

Internet history

Entry 3

Date 2022-11-14

Pictures 0

Listing price <u>View report</u>

source: carcraft.co.uk

Entry 2

Date 2021-08-10

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-08-09	
Pictures	0	
Listing price	View report	

source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-28
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	7
Total items failed	3

MOT #6	2023-11-20 12:50
MOT test number	238389176456
Result	✓ Passed
Next expiry date	2024-11-28
Advice Rear Brake pad(s) wearing thin Both (1.1.13 (a) (ii))	

MOT #5	2023-11-20 12:50	
MOT test number	917592999754	
Result	★ Failed	
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Rear Brake pad(s) wearing thin Both (1.1.13 (a) (ii))		
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #4	2022-11-29 15:52
MOT test number	996879353908
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #3 2022-11-23 12:19

MOT test number 987220248691

Result X Failed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Offside Front Windscreen wiper blade defective (3.4 (b) (i))

Fail Parking brake lever has excessive movement indicating incorrect adjustment Reaching end of its travel indicting the need for repair or adjustment. (1.1.6 (c))

MOT #2 2022-07-29 09:52

MOT test number 348514882504

Result \(\sqrt{Passed} \)

Advice Front Tyre worn close to legal limit/worn on edge both sides (5.2.3 (e))

MOT #1 2021-07-09 08:46

MOT test number 352704042591

Advice Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))

Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



funda scincos

VN18XLE

More info >

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this HYUNDAI had different number plates. ober of plates

CarCheck.co.uk page 8/11



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-07-17
Last registration	2023-11-20
Complete history	See info



Registration #1	2018-07-17	6 mi
Registration #2	2021-07-09	25.510 mi
Registration #3		11.777 es
Registration #4		11.777 es
Registration #5	2022-07-29	29.374 mi
Registration #6		11.777 es
Registration #7		
Registration #8		11.777 ea
		11.777 ea 11.777 ea

More info >

CarCheck.co.uk page 10/11



Car features

The HYUNDAI	factory car	options list	t is only av	ailable in the	premium report.

S0225 Air conditioning

S0295

S0482

S0501

S0566

S0567

S0569

View the complete HYUNDAI factory list for this vehicle here.

More info >

Safety ratings

NCAP rating	****
Adult	86%
Children	85%
Pedestrian	71%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1850 mm
Height	1645 mm
Length	4475 mm
Wheel base	2670 mm
Kerb weight	1464 kg
Max. allowed weight	1895 kg

Additional information

Fuel tank capacity	62 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page :	11/11