

Ford



### General information

Make	FORD
Model	FIESTA TITANIUM
Colour	Red
Year of manufacture	2010
Top speed	109 mph
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	95 BHP	0 < 101 A
Max. torque	128 Nm at 4.200 rpm	101 - 120 <sup>B</sup> <sub>C</sub>
Engine capacity	1.388 cc	121 - 140 P
Cylinders	4	141 - 165 F G
Fuel type	Petrol	166 - 185 H
Consumption city	37.7 mpg	186 - 225 J
Consumption extra urban	61.4 mpg	225+ L M
Consumption combined	49.6 mpg	
CO2 emission	133 g/km	
CO2 label	E	



# Internet history

Entry	1

Date Pictures 2021-01-30

10

Listing price

View report



source: autoonline.co.uk



### MOT history

MOT expiry date	2024-12-28
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	24
Total items failed	11

MOT #15	2023-12-29 15:39
MOT test number	189199318410
Result	✓ Passed
Next expiry date	2024-12-28
Advice Exhaust has a minor leak of exhaust gases backbox leak (6.1.2 (a))	

MOT #14	2023-12-28 15:41
MOT test number	894037512560
Result	🗙 Failed
FailNearside Front Tyre has a lump, caused by separation or partial failure ofAdviceExhaust has a minor leak of exhaust gases backbox leak (6.1.2 (a))Fail (ii))Nearside Rear Inner Tyre has a lump, caused by separation or partial fail	

MOT #13	2022-10-24 11:34
MOT test number	608522538902
Result	✓ Passed
Advice Tyre worn close to legal limit/worn on edge N/S/F AND N/S/R (5.2.3 (e))	



MOT #12	2022-10-22 09:36
MOT test number	236718890747
Result	🗙 Failed
<b>Fail</b> Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Tyre worn close to legal limit/worn on edge N/S/F AND N/S/R (5.2.3 (e))	
Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))	
FailNearside Front Position lamp not working (4.2.1 (a) (ii))	
<b>Fail</b> Offside Front Inner Tyre has a cut in excess of the requirements deep enough to r cords (5.2.3 (d) (i))	each the ply or
Fail Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1)	.2 (b))
Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b	) (ii))

MOT #11	2021-06-14 15:51
MOT test number	427772821699
Result	✓ Passed

MOT #10	)	2020-03-13 16:51
MOT test	: number	460251282071
Result		✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	)
Advice	Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge (5	5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice	Offside Rear Nail in tyre	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

LS10ASZ

report date: 2024-03-28





МОТ #9	2020-03-13 15:39
MOT test number	716353721065
Result	🗙 Failed
<b>Fail</b> Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	L4 (a) (ii))
Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on inner	r edge (5.2.3 (e))
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice Offside Rear Nail in tyre	

MOT #8	2019-04-06 07:	26
MOT test i	number 9623995707	41
Result	✓ Pass	ed
Advice Nearside Rear Tyre slightly damaged/cracking or perishing Wearing on inner edge (5.2.3 (d) (ii))		
Advice	Nearside Rear Nail in tyre	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Wearing on inner edge (5.2.3 (d) (ii))	

MOT #7		2018-04-07 08:14
MOT test	number	511946620073
Result		✓ Passed
Advice	Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Offside Front tyre worn inner edge	
Advice	Offside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)	
Advice	Nearside Front tyre worn inner edge	





MOT #6	2017-04-01 10:31
MOT test number	290418442873
Result	✓ Passed
MOT #5	2016-03-29 08:04
MOT test number	466301724159
Result	✓ Passed
Advice Nearside Rear Road wheel slightly damaged (4.2.A.1a)	
MOT #4	2015-04-29 14:30
MOT test number	989749215176
Result	✓ Passed
MOT #3	2015-04-28 17:06
MOT test number	838518115198
Result	🗙 Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Fail Nearside Front position lamp(s) not working (1.1.A.3b)	

MOT #2	2014-04-30 12:37
MOT test number	217960924422
Result	✓ Passed
Notice Rear tyres wearing low	
<b>Notice</b> Slight buckle in drivers side rear road wheel	

MOT #1	2013-04-15 10:36
MOT test number	207265303196
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 June 2024	✓ MOT Expires: 28 December 2024
Tax status	Valid until 1 June
Days left	33
MOT expiry date	28 December 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
***********	
********	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	7
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-28
Last registration	2023-12-29
Complete history	See info



Registration #1	2010-04-28	26 mi
Registration #2	2013-04-15	33.112 mi
Registration #3	2014-04-30	48.679 mi
Registration #4	2015-04-28	59.045 mi
Registration #5	2015-04-29	59.045 mi
Registration #6	2016-03-29	69.338 mi
Registration #7	2017-04-01	80.248 mi
Registration #8	2018-04-07	92.391 mi
Registration #9	2019-04-06	102.671 mi
Registration #10		11.777 est
Registration #11		11.777 esi
Registration #12		11.777 est
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.117 est
Registration #17		10.200 est
-		





#### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1495 kg
Additional information	
Fuel tank capacity	42
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	9E63133