





report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO 850 ENTERPRISE L1 BLUEHDI
Colour	White
Year of manufacture	2018
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-08-04

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-04-15
MOT pass rate	56 %
MOT passed	5
Failed MOT tests	4
Total advice items	10
Total items failed	5

MOT #9	2024-04-16 15:44
MOT test number	388633390054
Result	✓ Passed
Next expiry date	2025-04-15

MOT #8		2024-04-16 15:44
MOT test number		322360867087
Result		X Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	

MOT #7	2023-10-21 15:28
MOT test number	302508062783
Result	✓ Passed
Advice Offside Front Suspension arm pin or bush worn but not resulting in e (5.3.4 (a) (i))	excessive movement rear bush

MOT #6	2023-10-21 09:50
MOT test number	214342310169
Result	X Failed
Fail Nearside Front Position lamp not working (4.2.1 (a) (ii)) Advice Offside Front Suspension arm pin or bush worn but not resulting in (5.3.4 (a) (i))	excessive movement rear bush
Fail Registration plate lamp inoperative in the case of a single lamp or all la	amps (4.7.1 (b) (ii))

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #5 2022-10-01 10:48

MOT test number 154288069605

Result ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #4 2022-10-01 10:48

MOT test number 752526168550

Result X Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Pass with rectification Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #3 2021-09-21 13:31

MOT test number 413365658337

Result

Passed

MOT #2 2021-07-16 16:25

MOT test number 318465170539

Result ✓ Passed

Advice Offside door panel insecure

Advice Front wipers smear the screen

Advice Rear brakes binding slightly on both sides

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number
655860736033

Result

Pass with rectification
Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice
Front wipers smear the screen

Advice
Rear brakes binding slightly on both sides

Advice
Offside door panel insecure

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check





Tax status	Expired at 8 January 2024
Days left	111 days too late
MOT expiry date	15 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

\sim		
Owner	hictory	7
OWITCE	1113601	7

,		
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full		ROEN

	More info	>
Plate changes		
See in this check if this CITROEN had different number plates.		
Number of plates		
Current registration	NK SIE	
Plate since		
Current registration	NK NK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2018-06-29
Last registration	2024-04-16
Complete history	See info



Registration #1	2018-06-29	7 mi
Registration #2	2021-07-16	39.708 mi
Registration #3	2021-07-16	39.708 mi
Registration #4		11.777 es
Registration #5	2021-09-21	39.984 mi
Registration #6	2022-10-01	49.066 mi
Registration #7		11.777 esi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		10.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	***
Adult	56%
Children	74%
Pedestrian	63%
Safety systems	48%
Overall rating	59%
Video	see crash video

Dimensions & weight

Width	1810 mm
Height	1828 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1331 kg
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of seats	3
Number of axles	2
Engine number	JBHB3296682

CarCheck.co.uk page 12/12