



RENAULT



MJIITWC

report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE TOMTOM BOSE PACK DCI
Colour	Black
Year of manufacture	2011
Top speed	112 mph
0 - 100 km/h	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	78 kW / 106 HP / 110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	128 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-04
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-09-13
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	28
Total items failed	10

MOT #15	2023-08-15 13:34
MOT test number	745823678608
Result	✓ Passed
Next expiry date	2024-09-13
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #14	2023-08-14 10:48
MOT test number	859570716587
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Pass with rectification	Rear fog lamp not working (4.5.1 (a) (ii))
Fail	Nearside Rear Electrical wiring for braking components extremely deteriorated Wiring to parking brake motor (4.11 (b) (iii))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. Nearside effort low (1.2.1 (b) (i))
Fail	Nearside Parking brake inoperative on one side (1.4.1 (a))
Pass with rectification	Rear fog lamp tell-tale not working (4.9.1 (a) (ii))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**MOT #13** 2022-08-31 14:38**MOT test number** 899190633020**Result** ✓ Passed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Horn poor**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2022-08-31 08:20**MOT test number** 693302851522**Result** ✗ Failed**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Horn poor**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Fail** Reversing lamp inoperative (4.6.1 (a))**Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #11** 2021-08-28 08:01**MOT test number** 785407341564**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10** 2020-09-14 13:49**MOT test number** 824506449217**Result** ✓ Passed**MOT #9** 2019-04-17 10:20**MOT test number** 649058138622**Result** ✓ Passed**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2018-04-27 11:00**MOT test number** 526549877108**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2017-04-19 09:52**MOT test number** 129315643154**Result** ✓ Passed**MOT #6** 2017-04-19 07:30**MOT test number** 242360205084**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #5** 2016-04-26 10:50**MOT test number** 180405182302**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2016-04-22 10:27**MOT test number** 510819643117**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2015-04-20 12:30**MOT test number** 169640615192**Result** ✓ Passed**MOT #2** 2015-04-15 09:58**MOT test number** 688845505159**Result** ✗ Failed**Fail** Rear fog lamp switch faulty (1.3.1a)**MOT #1** 2014-05-12 10:03**MOT test number** 176982034158**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
13 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	13 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	D
<b>Single payment (12 months)</b>	£ 150,00,-
<b>Single six month payment</b>	£ 82,50,-
<b>Total payable by 12 monthly instalments</b>	£ 157,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT
Date of agreement	2024-03-29
Agreement type	RENAULT
Agreement term	RENAULT
Agreement number	RENAULT
Contact info	RENAULT

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-06-29
Last registration	2023-08-15
Complete history	<a href="#">See info</a>



Registration #1	2011-06-29	13 mi
Registration #2	2014-05-12	15.638 mi
Registration #3	2015-04-15	23.747 mi
Registration #4	2015-04-20	23.953 mi
Registration #5	2016-04-22	34.990 mi
Registration #6	2016-04-26	35.071 mi
Registration #7	2017-04-19	45.072 mi
Registration #8	2017-04-19	45.072 mi
Registration #9	2019-05-29	55.277 mi
Registration #10	2019-05-29	55.277 mi
Registration #11	2019-05-29	55.277 mi
Registration #12	2019-05-29	55.277 mi
Registration #13	2019-05-29	55.277 mi
Registration #14	2019-05-29	55.277 mi
Registration #15	2019-05-29	55.277 mi
Registration #16	2019-05-29	55.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1486 mm
Height	1637 mm
Length	4344 mm
Wheel base	2703 mm
Kerb weight	1385 kg
Max. allowed weight	1944 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D246598