





report date: 2024-03-28

### General information

Make	PEUGEOT
Model	207 SW S
Colour	Silver
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	95 BHP
Max. torque	136 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg



CarCheck.co.uk page 1/12



### Internet history

#### Entry 1

Date	2021-05-25	
Pictures	1	
Listing price	<u>View report</u>	



source: autotrader.co.uk

CarCheck.co.uk page 2/12



**MOT** history

**MOT #17** 2023-04-04 15:14

**MOT test number** 706487408499

**Result** ✓ Passed

Next expiry date 2024-04-18

MOT #16 2023-04-04 13:39

**MOT test number** 448076940114

Result X Failed

**MAJOR** Nearside Front Headlamp aim unable to be tested (4.1.2 (b))

MAJOR Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #15** 2022-04-19 15:03

**MOT test number** 670034463805

Result \( \sqrt{Passed} \)

Advice Nearside Rear Tyre slightly damaged/cracking or perishing on walls (5.2.3 (d) (ii))

**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #14** 2022-04-19 13:57

MOT test number 766444407844

Result X Failed

**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MAJOR** Offside Headlamp aim not tested (4.1.2 (b))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing on walls (5.2.3 (d) (ii))

**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MAJOR** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents

the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 3/12



KN11ZPF

report date: 2024-03-28

MOT #13 2021-03-26 13:07

**MOT test number** 835590441793

**Result** ✓ Passed

MOT #12 2021-03-26 10:05

**MOT test number** 204906074556

**Result** X Failed

**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11 2020-03-24 14:44

**MOT test number** 767480892966

**Result** ✓ Passed

**MOT #10** 2020-03-23 16:37

**MOT test number** 128074929561

Result X Failed

**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #9** 2019-02-26 15:27

**MOT test number** 153802720510

**Result** 
✓ Passed

MOT #8 2018-03-09 10:20

MOT test number 348894368711

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



Passed

**MOT #7** 2017-03-16 16:32

MOT test number 644787577267

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2017-03-15 12:21

**MOT test number** 238077632967

Result X Failed

**Fail** Rear Exhaust system not adequately supported Silencer support strap & rear mounting broken (7.1.1)

**Fail** Nearside Registration plate lamp not working (1.1.C.1d)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Rear position lamp(s) not working (1.1.A.3b)

**MOT #5** 2016-03-15 13:50

MOT test number 174004899484

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

Result

MOT #4 2016-03-15 10:11

MOT test number 957851688500

**Result** ★ Failed

**Fail** Nearside Stop lamp not working (1.2.1b)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)

MOT #3 2015-03-26 12:50

**MOT test number** 776845585090

CarCheck.co.uk page 5/12



MOT #2 2014-04-17 14:24

**MOT test number** 505537004173

**Result** ✓ Passed

**MOT #1** 2014-04-17 09:06

**MOT test number** 566937904115

**Result** X Failed

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice Exhaust rear mounting broken

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier metery	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NE ZIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-05-12
Last registration	2023-04-04
Complete history	See info



Registration #1	2011-05-12	9 mi
Registration #2	2014-04-17	27.322 mi
Registration #3	2014-04-17	27.322 mi
Registration #4	2015-03-26	36.357 mi
Registration #5	2016-03-15	44.682 mi
Registration #6	2016-03-15	44.682 mi
Registration #7	2017-03-15	52.739 mi
Registration #8	2017-03-16	52.748 mi
Registration #9	2018-03-09	58.929 mi
Registration #10	2019-02-26	66.144 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		D.777 es
Registration #19		

More info >

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1972 mm
Height	1555 mm
Length	4149 mm
Wheel base	2540 mm
Kerb weight	1273 kg
Max. allowed weight	1694 kg

## Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/

Number of axles 2

**Engine number** FGAN0986911