



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	HILUX INVINCIBLE D-4D DCP
Colour	Black
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	194 BHP
Max. torque	430 Nm at 1.400 rpm
Engine capacity	2.982 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-06-28
Pictures	14
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2021-06-26
Pictures	14
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-26
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	35
Total items failed	9

MOT #17

2023-10-27 16:45

MOT test number

747673342760

Result

✓ Passed

Next expiry date

2024-10-26

Advice

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #16

2023-10-24 12:09

MOT test number

321410636835

Result

✗ Failed

Fail

Parking brake efficiency below requirements (1.4.2 (a) (i))

Advice

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

MOT #15

2022-10-22 11:52

MOT test number

922144657976

Result

✓ Passed

Minor

Windscreen wiper blade defective Offside and nearside (3.4 (b) (i))



MOT #14

2021-10-25 09:41

MOT test number

822407159208

Result

✓ Passed

- Advice

Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice

Vehicle underside covered in a sealant or other material
- Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice

Wheel/tyre protruding beyond wheel arch all 4
- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice

Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))

**MOT #13**

2021-10-13 08:36

**MOT test number**

685581680441

**Result****✗ Failed**

- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Advice** Wheel/tyre protruding beyond wheel arch all 4
- Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Vehicle underside covered in a sealant or other material
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Outer Track rod end ball joint has slight play (2.1.3 (b) (i))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #12**

2020-10-15 10:26

**MOT test number**

303558974059

**Result****✓ Passed****MOT #11**

2019-04-16 10:32

**MOT test number**

329659587141

**Result****✓ Passed**

**MOT #10** 2018-04-12 09:55**MOT test number** 744051089817**Result** ✓ Passed**MOT #9** 2017-04-07 10:41**MOT test number** 348939877369**Result** ✓ Passed**MOT #8** 2016-04-05 15:50**MOT test number** 387709766007**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Front tyres worn on inner edges**MOT #7** 2016-04-04 15:19**MOT test number** 177227326782**Result** ✗ Failed**Advice** Front tyres worn on inner edges**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Parking brake lever has no reserve travel (3.1.6b)**MOT #6** 2016-04-04 15:15**MOT test number** 738192004848**Result** ✓ Passed

**MOT #5** 2016-03-31 13:29**MOT test number** 474828648070**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Centre Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Nearside Front tyre worn on inner shoulder**Fail** Parking brake lever has no reserve travel (3.1.6b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both discs (3.5.1i)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Offside Front tyre worn on inner shoulder**MOT #4** 2015-03-20 15:26**MOT test number** 499589775052**Result** ✓ Passed**MOT #3** 2014-03-28 14:03**MOT test number** 106277684403**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2013-03-26 16:49**MOT test number** 975305683020**Result** ✓ Passed**MOT #1** 2012-03-23 15:55**MOT test number** 477233482064**Result** ✓ Passed



Tax & MOT check

✖  
Untaxed

Tax expired:  
20 February 2024

✓  
MOT

Expires:  
26 October 2024

Tax status	Expired at 20 February 2024
Days left	70 days too late
MOT expiry date	26 October 2024
Full MOT history	<a href="#">See MOT history</a>





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-31
Last registration	2023-10-27
Complete history	<a href="#">See info</a>



Registration #1	2009-03-31	24 mi
Registration #2	2012-03-23	31.877 mi
Registration #3	2013-03-26	22.212 mi
Registration #4	2014-03-28	52.539 mi
Registration #5	2015-03-20	62.201 mi
Registration #6	2016-03-31	73.461 mi
Registration #7	2016-04-04	73.491 mi
Registration #8	2016-04-04	73.491 mi
Registration #9	2016-04-05	73.491 mi
Registration #10	2017-04-07	88.310 mi
Registration #11	2018-04-09	99.999 mi
Registration #12	2018-04-09	99.999 mi
Registration #13	2018-04-09	99.999 mi
Registration #14	2018-04-09	99.999 mi
Registration #15	2018-04-09	99.999 mi
Registration #16	2018-04-09	99.999 mi
Registration #17	2018-04-09	99.999 mi
Registration #18	2018-04-09	99.999 mi
Registration #19	2018-04-09	99.999 mi
Registration #20	2018-04-09	99.999 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1835 mm
Height	1810 mm
Length	5255 mm
Kerb weight	1885 kg
Max. allowed weight	2940 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1KD7547097