



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM
Colour	Black
Year of manufacture	-
Top speed	144 mph
0 - 60 mph	7.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	300 Nm at 1.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #10</b>	2020-08-17 13:52
<b>MOT test number</b>	457808951081
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-08-29
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Advice</b>	Both front lower suspension arms very rusty
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

<b>MOT #9</b>	2020-08-15 09:32
<b>MOT test number</b>	371010686882
<b>Result</b>	✗ Failed
<b>Advice</b>	Offside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Fail</b>	Nearside Rear Suspension arm pin or bush excessively worn pivot bush (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
<b>Fail</b>	Offside Front Position lamp not working (4.2.1 (a) (ii))
<b>Fail</b>	Offside Rear Suspension arm pin or bush excessively worn pivot bush (5.3.4 (a) (i))
<b>Advice</b>	Both front lower suspension arms very rusty

<b>MOT #8</b>	2019-08-12 11:07
<b>MOT test number</b>	110376459460
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2018-08-21 10:43
<b>MOT test number</b>	897966515716
<b>Result</b>	✓ Passed
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened inner edge (1.1.14 (a) (ii))
<b>Advice</b>	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))



**MOT #6** 2017-08-25 08:18**MOT test number** 126462974407**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner edge (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit 235/40/18 (4.1.E.1)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Tyre worn close to the legal limit 235/40/18 (4.1.E.1)**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5** 2016-08-30 09:27**MOT test number** 391374460717**Result** ✓ Passed**MOT #4** 2015-08-13 10:23**MOT test number** 673831091994**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2014-08-28 11:31**MOT test number** 865780744243**Result** ✓ Passed**MOT #2** 2014-08-28 11:10**MOT test number** 227820144248**Result** ✗ Failed**Fail** Offside Front Wheel nut(s) missing (4.2.A.1e)



MOT #1	2013-07-05 14:50
MOT test number	288736883456
Result	✓ Passed
<div>Notice Nail in nearside front tyre</div>	



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2010-07-22
Last registration	2020-08-17
Complete history	<a href="#">See info</a>



Registration #1	2010-07-22	18 mi
Registration #2	2013-07-05	29.419 mi
Registration #3	2014-08-28	40.924 mi
Registration #4	2014-08-28	40.924 mi
Registration #5	2015-08-13	50.432 mi
Registration #6	2016-08-30	58.655 mi
Registration #7	2019-08-20	59.377 mi
Registration #8	2019-08-20	59.377 mi
Registration #9	2019-08-20	59.377 mi
Registration #10	2019-08-20	59.377 mi
Registration #11	2019-08-20	59.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1886 mm
Height	1512 mm
Length	4830 mm
Wheel base	2850 mm
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

**Engine number**

AJ03382