



GL59EOH

report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	13.9 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	101 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg



**MOT history**

<b>MOT #14</b>	2021-10-29 16:17
<b>MOT test number</b>	303253209304
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-10-28
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Minor</b>	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

<b>MOT #13</b>	2021-10-21 13:08
<b>MOT test number</b>	730600764348
<b>Result</b>	✗ Failed
<b>Minor</b>	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Fail</b>	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))

<b>MOT #12</b>	2020-10-16 12:31
<b>MOT test number</b>	595638868921
<b>Result</b>	✓ Passed

<b>MOT #11</b>	2020-10-15 10:18
<b>MOT test number</b>	145102306091
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside Front temporary wheel fitted
<b>Fail</b>	Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

<b>MOT #10</b>	2019-10-14 12:21
<b>MOT test number</b>	667182546395
<b>Result</b>	✓ Passed

**MOT #9** 2018-10-01 09:30**MOT test number** 953685084758**Result** ✓ Passed

**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened rear of disc corroded (1.1.14 (a) (ii))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened rear of disc corroded (1.1.14 (a) (ii))

**MOT #8** 2017-10-10 12:04**MOT test number** 726621360634**Result** ✓ Passed

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #7** 2017-10-10 09:59**MOT test number** 754673450137**Result** ✗ Failed

**Advice** Nearside Front Tyre worn close to the legal limit on 1.6 mm 205/55/16 (4.1.E.1)

**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Offside Rear Stop lamp emits other than a steady red light (1.2.1e)

**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Nearside Rear Stop lamp emits other than a steady red light (1.2.1e)

**Advice** Nearside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)



<b>MOT #6</b>	2016-10-21 08:33
---------------	------------------

<b>MOT test number</b>	456490691532
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #5</b>	2015-10-22 13:14
---------------	------------------

<b>MOT test number</b>	489784001757
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #4</b>	2014-12-12 09:28
---------------	------------------

<b>MOT test number</b>	596456544309
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #3</b>	2013-12-12 10:27
---------------	------------------

<b>MOT test number</b>	615636643389
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>MOT #2</b>	2012-12-29 09:44
---------------	------------------

<b>MOT test number</b>	205234062336
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #1</b>	2012-10-27 08:58
---------------	------------------

<b>MOT test number</b>	455491402389
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>GL59EOH</b>
Plate since	2019-03-29
Current registration	<b>GL59EOH</b>
Plate since	2019-03-29

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-12-10
Last registration	2021-10-29
Complete history	<a href="#">See info</a>



Registration #1	2009-12-10	12 mi
Registration #2	2012-10-27	24.660 mi
Registration #3	2012-12-29	25.736 mi
Registration #4	2013-12-12	27.492 mi
Registration #5	2014-12-12	29.040 mi
Registration #6	2015-10-22	35.083 mi
Registration #7	2016-10-21	41.048 mi
Registration #8	2017-10-10	49.372 mi
Registration #9	2018-10-10	55.377 mi
Registration #10	2019-10-10	61.377 mi
Registration #11	2020-10-10	67.377 mi
Registration #12	2021-10-10	73.377 mi
Registration #13	2022-10-10	79.377 mi
Registration #14	2023-10-10	85.377 mi
Registration #15	2024-10-10	91.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1840 mm
Height	1501 mm
Length	4472 mm
Wheel base	2640 mm
Kerb weight	1340 kg
Max. allowed weight	1845 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	9K16398