





General information

| Make | AUDI |
|---------------------|------------------------|
| Model | A4 TDI S LINE |
| Colour | Blue |
| Year of manufacture | 2008 |
| Top speed | 133 mph |
| 0 - 60 mph | 9.2 seconds |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| Power | 188 BHP |
|-------------------------|---------------------|
| Max. torque | 320 Nm at 2.500 rpm |
| Engine capacity | 1.968 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 36.7 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 47.9 mpg |
| CO2 emission | 143 g/km |
| CO2 label | F |







| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-01-27 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| MOT expiry date | 2025-03-13 |
|--------------------|------------|
| MOT pass rate | 76 % |
| MOT passed | 13 |
| Failed MOT tests | 4 |
| Total advice items | 27 |
| Total items failed | 6 |

| MOT #17 | 2024-03-08 08:47 |
|---|-------------------------|
| MOT test number | 158623987232 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-13 |
| Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i)) | |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weak | xened (1.1.14 (a) (ii)) |

MOT #162024-03-08 08:47MOT test number252600452141Result× FailedPass with rectificationNearside Headlamp aim too low (4.1.2 (a))AdviceRear Brake pad(s) wearing thin (1.1.13 (a) (ii))AdviceNearside Rear Coil spring corroded (5.3.1 (b) (i))AdviceRear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

| MOT #15 | 2023-03-13 15:39 |
|-----------------|------------------|
| MOT test number | 770874566538 |
| Result | ✓ Passed |





| MOT #14 | 2022-03-09 17:26 |
|---|------------------|
| MOT test number | 152040674641 |
| Result | ✓ Passed |
| | |
| MOT #13 | 2021-03-12 18:09 |
| MOT test number | 540120120777 |
| Result | ✓ Passed |
| Advice Tyre worn close to legal limit/worn on edge all tyres (5.2.3 (e)) | |
| Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) | |
| Advice Tyre slightly damaged/cracking or perishing all tyres. (5.2.3 (d) (ii)) | |
| Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) | |

| MOT #12 | 2020-03-14 08:57 |
|----------|---|
| MOT test | number 131019720008 |
| Result | ✓ Passed |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice | Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b)) |

| MOT #11 | 2020-03-13 11:37 |
|--|------------------|
| MOT test number | 397961338533 |
| Result | 🗙 Failed |
| Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii) |)) |





| MOT #10 | | 2018-11-21 12:32 |
|----------|---|------------------|
| MOT test | number | 324171036397 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Front Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) | |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| МОТ #9 | 2017-12-04 11:56 |
|---|------------------|
| MOT test number | 916348327629 |
| Result | ✓ Passed |
| Advice Nearside Front Shock absorber has a light misting of oil (2.7.3) | |

| МОТ #8 | | 2017-12-04 11:56 |
|---|---|------------------|
| MOT test number | | 257571040287 |
| Result | | 🗙 Failed |
| Pass with rectification | Offside Headlamp aim too low and too far to the right. (1.8) | |
| Advice Nearside Front Shock absorber has a light misting of oil (2.7.3) | | |
| Pass with rectification | Nearside Registration plate lamp not working (1.1.C.1d) | |
| Pass with rectification | Offside Windscreen washer provides insufficient washer liquid (| 3.2.3) |



wrssever report date: 2024-03-28

| MOT #7 | 2016-07-28 09:08 |
|---|------------------|
| MOT test number | 930066827973 |
| Result | ✓ Passed |
| Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Nearside Front Shock absorber has a light misting of oil (2.7.3) | |

| MOT #6 | 2015-07-21 09:56 |
|-----------------|------------------|
| MOT test number | 139182705248 |
| Result | ✓ Passed |

| MOT #5 | 2014-08-01 16:15 |
|-----------------|------------------|
| MOT test number | 295663714267 |
| Result | ✓ Passed |

| МОТ #4 | 2014-08-01 10:04 |
|---|------------------|
| MOT test number | 856923414240 |
| Result | 🗙 Failed |
| Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) | |

| MOT #3 | | 2013-07-29 11:14 |
|----------|--|------------------|
| MOT test | number | 765810313257 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |





| MOT #2 | 2012-07-26 15:43 |
|-----------------|------------------|
| MOT test number | 857628702267 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2011-08-11 11:54 |
| MOT test number | 247723921221 |
| Result | ✓ Passed |



Tax & MOT check

| √ Taxed | √ МОТ |
|------------------------|--|
| Tax due: 1 May 2025 | Expires: 13 March 2025 Valid until 1 May |
| Days left | 367 |
| MOT expiry date | 13 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--------|
| Date | FERRE |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | e et a |
| Date | * |
| Category | AMP |
| Туре | |

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| ************ | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this AUDI had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 19 |
| First mileage registration | 2008-11-27 |
| Last registration | 2024-03-08 |
| Complete history | See info |



| Registration #1 | 2008-11-27 | 19 mi |
|--|------------|--|
| Registration #2 | 2011-08-11 | 42.201 mi |
| Registration #3 | 2012-07-26 | 51.713 mi |
| Registration #4 | 2013-07-29 | 64.615 mi |
| Registration #5 | 2014-08-01 | 75.157 mi |
| Registration #6 | 2014-08-01 | 75.157 mi |
| Registration #7 | 2015-07-21 | 83.537 mi |
| Registration #8 | 2016-07-28 | 87.614 mi |
| Registration #9 | 2017-12-04 | 97.442 mi |
| Registration #10 | 2017-12-04 | 97.442 mi |
| | | |
| Registration #11 | | 11.227 mi |
| Registration #11 Registration #12 | | 00.000 est |
| - | | 01.000 est 01.000 est 01.000 est |
| Registration #12 | | 01,000 est 01,000 est 01,000 est 01,000 est |
| Registration #12 Registration #13 | | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |
| Registration #12 Registration #13 Registration #14 | | 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est |
| Registration #12 Registration #13 Registration #14 Registration #15 | | 01,000 46 01,000 46 01,000 46 01,000 46 01,000 46 01,000 46 |
| Registration #12 Registration #13 Registration #14 Registration #15 Registration #16 | | 00,000 460 00,000 460 00,000 460 00,000 460 00,000 460 00,000 460 00,000 460 00,000 460 |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| \$0501 | |
| S0566 | |
| \$0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1765 mm |
| Height | 1423 mm |
| Length | 4286 mm |
| Wheel base | 2578 mm |
| Kerb weight | 1385 kg |
| Max. allowed weight | 1945 kg |
| Additional information | |
| Fuel tank capacity | 55 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 14/14 |

| Number of axles | 2 |
|-----------------|------------|
| Engine number | CBA 429661 |