



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	VERSO D-4D ICON
Colour	White
Year of manufacture	2015
Top speed	112 mph
0 - 60 mph	12.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 2.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-10-19
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-06
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	31
Total items failed	9

MOT #15 2023-10-02 15:01

MOT test number 227944494614

Result ✓ Passed

Next expiry date 2024-10-06

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))

MOT #14 2022-10-07 12:03

MOT test number 127521337919

Result ✓ Passed

- Advice** Front Tyre worn close to legal limit/worn on edge both nearside and offside (5.2.3 (e))
- Advice** Slight smear from the front wiper blades
- Advice** Tyre pressure lamp is illuminated on the dash
- Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))
- Advice** Oil leak

**MOT #13**

2022-10-07 11:38

MOT test number

742999126937

Result**✗ Failed****Advice**

Oil leak

Minor

Battery insecure but not likely to fall from carrier (4.13 (a) (i))

Fail

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail

Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Advice

Front Tyre worn close to legal limit/worn on edge both nearside and offside (5.2.3 (e))

Advice

Slight smear from the front wiper blades

Fail

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice

Tyre pressure lamp is illuminated on the dash

Fail

Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both nearside and offside (4.7.1 (b) (ii))

Fail

Nearside Rear Position lamp not working (4.2.1 (a) (ii))

MOT #12

2021-07-13 14:35

MOT test number

585168477285

Result**✓ Passed****MOT #11**

2021-07-12 12:54

MOT test number

609627297325

Result**✗ Failed****Fail**

Offside Front Road wheel fixing missing (5.2.1 (a) (i))

**MOT #10** 2021-01-13 15:57**MOT test number** 468303151982**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively both (1.1.14 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9** 2020-07-07 12:32**MOT test number** 446313635977**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #8** 2020-07-07 08:49**MOT test number** 993072181646**Result** ✗ Failed**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #7** 2019-12-16 15:55**MOT test number** 206958620642**Result** ✓ Passed

**MOT #6** 2019-06-04 09:55**MOT test number** 524828087660**Result** ✓ Passed**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #5** 2018-12-04 14:59**MOT test number** 753697027314**Result** ✓ Passed**MOT #4** 2018-06-04 13:13**MOT test number** 275112319740**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-06-04 12:17**MOT test number** 155666988060**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #2** 2017-12-05 14:18**MOT test number** 486133995983**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



MOT #1	2017-06-05 15:02
MOT test number	991614349598
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
6 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	6 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2015-05-29
Current registration	*****
Plate since	2015-05-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2015-05-26
Last registration	2023-10-02
Complete history	See info



Registration #1	2015-05-26	16 mi
Registration #2	2017-06-05	38.362 mi
Registration #3	2017-12-05	45.053 mi
Registration #4	2018-06-04	56.175 mi
Registration #5	2018-06-04	56.175 mi
Registration #6	2018-12-04	82.341 mi
Registration #7	2019-06-04	93.993 mi
Registration #8	2019-12-16	114.413 mi
Registration #9	2020-07-07	128.672 mi
Registration #10	2020-06-04	128.672 mi
Registration #11	2020-06-04	128.672 mi
Registration #12	2020-06-04	128.672 mi
Registration #13	2020-06-04	128.672 mi
Registration #14	2020-06-04	128.672 mi
Registration #15	2020-06-04	128.672 mi
Registration #16	2020-06-04	128.672 mi
Registration #17	2020-06-04	128.672 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1630 mm
Length	4460 mm
Wheel base	2780 mm
Kerb weight	1620 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	N470649294