



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX20 CLASSIC
Colour	Blue
Year of manufacture	2012
Top speed	104 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	130 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-10-14
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-29
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	19
Total items failed	4

MOT #13	2023-10-30 13:47
MOT test number	924138415528
Result	✓ Passed
Next expiry date	2024-10-29

MOT #12	2022-10-18 11:21
MOT test number	357267188940
Result	✓ Passed

MOT #11	2021-10-25 09:45
MOT test number	742435269246
Result	✓ Passed

**MOT #10**

2021-10-19 13:25

MOT test number

308024821255

Result**✗ Failed**

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9

2020-12-01 16:15

MOT test number

658204856350

Result**✓ Passed**

- Advice** Nearside Rear has a slight brake bind
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))

MOT #8

2020-12-01 13:18

MOT test number

846849766503

Result**✗ Failed**

- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Nearside Rear has a slight brake bind
- Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #7** 2019-12-19 15:22**MOT test number** 998149511012**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**MOT #6** 2019-12-19 15:22**MOT test number** 553459556225**Result** ✗ Failed**Pass with rectification** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Pass with rectification** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Rear Nail in tyre**MOT #5** 2019-05-01 14:44**MOT test number** 262742613944**Result** ✓ Passed**MOT #4** 2018-04-19 14:41**MOT test number** 166195074339**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**MOT #3** 2017-04-28 13:24**MOT test number** 148700248800**Result** ✓ Passed**Advice** Slight damage too near side front tyre outer side wall.**MOT #2** 2016-05-03 11:19**MOT test number** 470584047128**Result** ✓ Passed



MOT #1	2015-04-08 15:55
MOT test number	736568995097
Result	✓ Passed
Notice	Nearside front wiper blade split
Notice	Nail in nearside rear tyre



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
29 October 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	29 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	YY12KSO
Plate since	2019-09-28
Current registration	YY12KSO
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-05-21
Last registration	2023-10-30
Complete history	See info



Registration #1	2012-05-21	7 mi
Registration #2	2015-04-08	18.357 mi
Registration #3	2016-05-03	22.612 mi
Registration #4	2017-04-28	25.991 mi
Registration #5	2018-04-19	29.967 mi
Registration #6	2019-05-01	37.635 mi
Registration #7	2019-12-19	41.132 mi
Registration #8	2019-12-19	41.132 mi
Registration #9	2020-05-20	45.277 mi
Registration #10	2020-05-20	45.277 mi
Registration #11	2020-05-20	45.277 mi
Registration #12	2020-05-20	45.277 mi
Registration #13	2020-05-20	45.277 mi
Registration #14	2020-05-20	45.277 mi
Registration #15	2020-05-20	45.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FACZ519415