





report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Blue
Year of manufacture	2006
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg
CO2 emission	259 g/km
CO2 label	М



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 3

Date 2022-01-12


Pictures 75

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-09-08

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-09-07

Pictures 75

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-02-21
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	28
Total items failed	9

MOT #23		2024-02-22 12:22
MOT test	number	642644928979
Result		✓ Passed
Next expi	ry date	2025-02-21
Advice	Rear Inner Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Advice	Tyre slightly damaged/cracking or perishing all (5.2.3 (d) (ii))	
Advice	Front Oil leak, but not excessive oil filter (8.4.1 (a) (i))	

MOT #22	2023-01-26 15:58
MOT test number	195732448014
Result	✓ Passed

MOT #21	2023-01-20 13:24	
MOT test number	991736880342	
Result	X Failed	
Fail Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))		
Minor Nearside Steering rack gaiter damaged or deteriorated, but preventing (i))	ng the ingress of dirt (2.1.3 (g)	

MOT #20	2022-01-21 10:59
MOT test number	899654117279
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

MOT #19 2021-03-25 10:12

MOT test number 250700578802

MOT #18 2020-06-01 14:33

MOT test number 827458231943

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #17 2019-05-07 09:25

MOT test number 928966377939

Result ✓ Passed

MOT #16 2018-05-09 13:21

MOT test number 711397376893

MOT #15 2018-05-09 08:15

MOT test number 948263715588

Result X Failed

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure outer side wall (4.1.D.1b)

Fail Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure outer side wall (4.1.D.1b)

MOT #14 2017-06-02 09:25

MOT test number 882379458943

Result ✓ Passed

CarCheck.co.uk page 4/14



MOT #13 2017-05-30 08:47

MOT test number 102862283327

Result

× Failed

Fail Offside Front Outer Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

Fail Nearside Front Outer Body or chassis has excessive corrosion, seriously affecting its strength within 30cm of the body mountings (6.1.B.2)

Advice

Oil leak

MOT #12 2016-07-13 15:20

MOT test number 759553511290

Result \(\sqrt{Passed} \)

Advice Front registration plate delaminated but not likely to be misread (6.3.1d)

Advice Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

MOT #11 2016-07-13 15:20

MOT test number 424859926421

Result ★ Failed

Pass with rectification Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)

Advice Front registration plate delaminated but not likely to be misread (6.3.1d)

Advice Nearside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

MOT #10 2015-07-17 12:41

MOT test number 599488395101

Advice Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

Advice Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

CarCheck.co.uk page 5/14



Result

BY51ANR report date: 2024-03-28

× Failed

MOT #9 2015-07-15 16:33

MOT test number 709866495176

Advice Offside Rear Lower Shock absorber has a slightly worn bush (2.7.4)

Advice Nearside Rear Brake hose has slight corrosion to ferrules (3.6.B.4e)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)

Fail Nearside Front Mechanical brake component has restricted free movement (3.5.1k)

MOT #8 2014-07-15 10:16

MOT test number 258736794153

Result \rightarrow Passed

Notice Under-trays fitted obscuring some underside components

Notice 2 front tyres 2rear tyres cracked in tread not cord

MOT #7 2014-04-18 11:55

MOT test number 327768604131

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)

Notice Under-trays fitted obscuring some underside components

Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)

Notice Engine covers fitted obscuring some components in the engine bay

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #6	2014-04-17 08:56
MOT test number	487347204162
Result	X Failed
Fail Offside Rear Brake pipe excessively corroded (3.6.B.2c)	
Notice Under-trays fitted obscuring some underside components	
Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)	
Fail Offside Front Brake pipe excessively corroded (3.6.B.2c)	
Advice Nearside Front Brake pipe slightly corroded (3.6.B.2c)	
Notice Engine covers fitted obscuring some components in the engine bay	

Notice Engine covers fitted obscuring some components in the engine bay	
MOT #5	2013-07-29 13:43
MOT test number	828330413266
Result	✓ Passed
MOT #4	2012-08-24 09:48
MOT test number	707097732288
Result	✓ Passed
MOT #3	2011-08-30 09:41
MOT test number	668542041288
Result	✓ Passed
MOT #2	2010-07-26 10:07
MOT test number	144237200272
Result	✓ Passed
MOT #1	2009-07-23 10:06
MOT test number	231174109264
Result	✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 January
Days left	247
MOT expiry date	21 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

e when miscory		
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		AR

manage and the same and the sam		

	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2006-09-11
Last registration	2024-02-22
Complete history	See info



Registration #1	2006-09-11	28 mi
Registration #2	2009-07-23	10.932 mi
Registration #3	2010-07-26	14.142 mi
Registration #4	2011-08-30	19.736 mi
Registration #5	2012-08-24	24.144 mi
Registration #6	2013-07-29	26.680 mi
Registration #7	2014-04-17	30.288 mi
Registration #8	2014-04-18	30.291 mi
Registration #9	2014-07-15	30.628 mi
Registration #10	2015-07-15	32.870 mi
Registration #11	2015-07-17	32.870 mi
Registration #12	2016-07-13	35.057 mi
Registration #13	2016-07-13	35.057 mi
Registration #14	2017-05-30	36.778 mi
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		9.70 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es
Registration #26		11.777 es
CarCheck.co.uk		page 13/14

More info >



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	69 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	542328359FG

CarCheck.co.uk page 14/14